

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22007253/UGA3Q2**Date:** 19/02/2023REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | Allianz Insurance Singapore Pte. Ltd. | Policy No: | SP2001320693-01 |
| Claimant Vehicle No : | SGW7558H | Insured Vehicle No : | SLP138K |
| Date of Loss: | 28/07/2022 | Nature of Claim: | TP |
| | | Claim No: | N/A |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SGW7558H | Engine No: | FB25Y252623 |
| Make & Model: | SUBARU OUTBACK, 2.5 I-S CVT AWD SR (A) | Chassis No: | JF2BS9KC2GG036073 |
| Reg. Date: | 18/05/2016 (Man. Year: 2016) | Odometer: | 173998 km |
| Colour: | Silver | | |
| Engine Capacity: | 2498 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/60 R18 | Rear Tyre Size: | 225/60 R18 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 1,637.12 | 706.32 | 930.80 | 56.86 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 800.00 | 550.00 | 250.00 | 31.25 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 2,437.12 | 1,256.32 | 1,180.80 | 48.45 |
| Approved Total (Overridden) (S\$) | | 1,000.00 | | |
| (S\$) | 2,437.12 | 1,000.00 | 1,437.12 | 58.97 |
| + GST 7.00/7.00% (S\$) | 170.60 | 70.00 | 100.60 | 58.97 |
| Nett Amount (S\$) | 2,607.72 | 1,070.00 | 1,537.72 | 58.97 |
| + Car Rental (2.0 x S\$100.00/day) (S\$) | | 200.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 1,272.00 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 30/07/2022 | | |
| Date Inspected: | 18/08/2022 | Inspected At: | Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716 |
| Estimated Period of Repair: | 2.0 days | | |

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 19 Feb 2023) | |
| Parts: | N/A | SUBARU OUTBACK 2.5 I-S CVT AWD SR (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGW7558H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-------------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented / Deformed | 653.40 FL | *653.40 FL |
| 2 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 39.00 FL | *39.00 FL |
| 3 | 2 | | *REAR BUMPER SIDE HOLDER -LH/RH | Not Necessary | 72.00 FL | *- FL |
| 4 | 1 | | *REAR BUMPER OUTER TOP GARNISH ,BLACK | Serviceable | 420.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER LOWER COVER ,CENTRE -SILVER | Deformed | 190.50 FL | *190.50 FL |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT | Serviceable | 396.50 FL | *- FL |
| 7 | 1 | | *SET REAR BUMPER SENSOR | Serviceable | 220.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|---------------|
| Sub Total (\$\$) | 1,991.40 | 882.90 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 354.28 | 176.58 |
| Total Parts (\$\$) | 1,637.12 | 706.32 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|--------------------------------|---------------|
| Labour Items | | | | |
| 1 | TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS | New | 350.00 | 200.00 |
| 2 | TO RESPRAY PAINT ON ACCIDENT PORTIONS | New | 400.00 | 300.00 |
| 3 | TO TRANSFER REAR BUMPER | New | 50.00 | 50.00 |
| | | | Gross Labour Cost (S\$) | 800.00 |
| | | | | 550.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >