

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22007255/TPA3Q2**Date:** 18/01/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002753
Claimant Vehicle No : SHC3416D **Insured Vehicle No :** SGC2200C
 Date of Loss: 26/07/2022 Nature of Claim: TP Claim No: MPC2022D0003974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3416D**
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU191405
 Reg. Date: 01/03/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU141436
 Colour: Blue Odometer: 502187 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,885.52	975.12	910.40	48.28
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	910.00	630.00	280.00	30.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,806.52	1,616.12	1,190.40	42.42
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,806.52	1,300.00	1,506.52	53.68
+ GST 7.00/7.00% (S\$)	196.46	91.00	105.46	53.68
Nett Amount (S\$)	3,002.98	1,391.00	1,611.98	53.68
+ Loss of Use (2.5 x S\$40.00/day) (S\$)		100.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,805.98		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment: 27/07/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 27/07/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHC3416D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Torn	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	138.10 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER LOWER CTR MOULDING	Cracked	155.00 FL	*155.00 FL
8	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
9	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
10	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 F	*- F
11	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
12	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,285.65	1,192.65
- List Item Discount on L Items 20.00/20.00% (\$)	400.13	217.53
Total Parts (\$)	1,885.52	975.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
			Gross Labour Cost (\$\$)	910.00
				630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >