

Vehicle Damage Assessment Report for [SHC3416D]

Estimate Created: 30/07/2022 17:04 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 02/11/2022 23:15 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Ioniq
Engine Type			
License Plate Number	SHC3416D	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	502,187.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$1300.00 with 2 days for repair

Insurlogic 1 (02/11/2022 23:14)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER COVER		1	459.40	-20.00 %	367.52
REAR BUMPER CLIPS		1	22.00	-20.00 %	17.60
REAR BUMPER CTR MOULDING ASSY		1	451.25	-20.00 %	361.00
REAR BUMPER LOWER CTR MOULDING		1	155.00	-20.00 %	124.00
REAR NUMBER PLATE WITH COVER		1	55.00	0.00 %	55.00
REAR RUBBER MAT		1	50.00	0.00 %	50.00
Parts Subtotal					975.12

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
MISC		1.0	11.00	0.00 %	11.00
Materials Subtotal					11.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/REPAIR ACCIDENT AFFECTED ITEMS AND AREA	RnR	350.00	0.00 %	350.00
RNR REVERSE SENSOR	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price	
ACCIDENT AFFECTED AREA	Full spray	250.00	0.00 %	250.00	
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		380.00	
				Paint Labor Subtotal	250.00
				Labor Subtotal	630.00

Summary

Repair Cost	1,616.12
Discount(20 %)	(316.12)

	1,300.00
Excess	(0.00)
GST(0.00 %)	0.00
<hr/>	
Grand Subtotal	1,300.00