

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007256/APA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210131956
Claimant Vehicle No :	SJG7667A	Insured Vehicle No :	GBD5109T
Date of Loss:	21/07/2022	Nature of Claim:	TP
		Claim No:	1468723161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG7667A		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030200069
Reg. Date:	15/01/2015 (Man. Year: 2014)	Chassis No:	WDD2050402F038165
Colour:	Blue	Odometer:	181094 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,116.80	7,083.79	28,033.01	79.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,410.00	1,670.00	4,740.00	73.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,526.80	8,753.79	32,773.01	78.92
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	41,526.80	7,000.00	34,526.80	83.14
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,542.45		
Global Sum Settlement (S\$)		7,500.00		

INSPECTION

Date of Assignment:	26/07/2022	
Date Inspected:	26/07/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,194.50 FL	*1,688.00 FL
2	1	*REAR BUMPER TOWING COVER	Missing	88.00 FL	*35.00 FL
3	1	*REAR BUMPER EXHAUST COVER GARNISH	Not Necessary	385.70 FL	*- FL
4	1	*REAR BUMPER REVERSE SENSOR (6 PCS)	Damaged (2 PCS ONLY)	1,613.40 FL	*537.80 FL
5	6	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	402.00 FL	*150.00 FL
6	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	798.00 FL	*- FL
7	1	*REAR BUMPER CENTER UPPER BRACKET	Cracked	285.90 FL	*285.90 FL
8	1	*REAR BUMPER BOTTOM CENTER GARNISH	Not Necessary	198.50 FL	*- FL
9	1	*REAR BUMPER LOWER GARNISH	Deformed	298.70 FL	*298.70 FL
10	1	*REAR BUMPER LOWER GARNISH CHROME	Cut	346.00 FL	*346.00 FL
11	1	*REAR BUMPER SIDE RETAINER	O/S Necessary	148.00 FL	*74.00 FL
12	2	*REAR BUMPER LOWER BRACKET (CENTER)	Not Necessary	130.00 FL	*- FL
13	1	*REAR BUMPER SMART SENSOR CONTROL UNIT	Not Necessary	374.00 FL	*- FL
14	1	*REAR BUMPER SMART SENSOR	Not Necessary	169.00 FL	*- FL
15	1	*REAR BUMPER SMART SENSOR MOTOR C/W CABLE	Not Necessary	305.80 FL	*- FL
16	1	*REAR BUMPER REINFORCEMENT	Dented	725.60 FL	*725.60 FL
17	1	*REAR BUMPER LOWER COVER RH	Torn	198.70 FL	*198.70 FL
18	2	*REAR FENDER	Not Necessary	5,510.00 FL	*- FL
19	2	*REAR FENDER DRAIN GARNISH	Not Necessary	196.00 FL	*- FL
20	2	*REAR FENDER COWLING	Not Necessary	411.40 FL	*- FL
21	2	*REAR FENDER INNER TRIM	Not Necessary	971.80 FL	*- FL
22	1	*REAR FENDER AIR VENT RH	Not Necessary	156.30 FL	*- FL
23	1	*REAR WINDSCREEN GLASS C/W MOULDING	Not Necessary	1,360.00 FL	*- FL
24	1	*TAILLAMP	O/S Cracked	1,651.20 FL	*748.00 FL
25	2	*TAILLAMP PANEL	Repair	1,972.00 FL	*- FL
26	1	*TAILLAMP LOWER BRACKET	O/S Cracked	407.20 FL	*85.00 FL
27	1	*BOOTLID	Dented	2,458.90 FL	*2,323.00 FL
28	1	*BOOTLID REVERSE CAMERA	Not Necessary	1,650.00 FL	*- FL
29	1	*BOOTLID CENTER MOULDING	Not Necessary	159.00 FL	*- FL
30	1	*BOOTLID LOGO	Necessary	98.70 FL	*98.70 FL
31	1	*BOOTLID OUTER SWITCH BUTTON	Not Necessary	183.00 FL	*- FL
32	4	*BOOTLID STOPPER	Not Necessary	180.00 FL	*- FL
33	2	*BOOTLID HINGE	Not Necessary	262.00 FL	*- FL
34	1	*BOOTLID INSULATOR	Not Necessary	598.00 FL	*- FL
35	1	*BOOTLID TOP LOCK	Not Necessary	385.90 FL	*- FL
36	1	*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
37	1	*BOOTLID WEATHERSTRIP	Cut	198.70 FL	*198.70 FL
38	1	*BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	168.00 FL	*- FL
39	1	*REAR END PANEL	Repair	1,460.00 FL	*- FL
40	1	*REAR END PANEL TOP GARNISH	Not Necessary	298.50 FL	*- FL
41	1	*REAR WELL PANEL TRIM	Not Necessary	328.00 FL	*- FL
42	1	*REAR FLOOR PANEL (WELL PANEL)	Not Necessary	986.00 FL	*- FL
43	1	*REAR FLOOR PANEL SPONGE	Not Necessary	190.00 FL	*- FL
44	1	*REAR FLOOR PANEL COVER BOARD	Not Necessary	649.00 FL	*- FL
45	1	*REAR FLOOR UNDER SIDE GARNISH RH	Not Necessary	248.00 FL	*- FL
46	1	*CENTRE EXHAUST PIPE	Not Necessary	1,930.00 FL	*- FL
47	2	*CENTRE EXHAUST PIPE GASKET	Not Necessary	172.00 FL	*- FL
48	1	*CENTRE EXHAUST PIPE INSULATOR	Not Necessary	223.00 FL	*- FL
49	1	*REAR EXHAUST BOX LH	Not Necessary	1,630.00 FL	*- FL
50	2	*REAR EXHAUST INSULATOR	Not Necessary	411.60 FL	*- FL
51	4	*REAR EXHAUST MOUNTING	Not Necessary	388.00 FL	*- FL
52	2	*REAR EXHAUST MOUNTING BRACKET	Not Necessary	150.00 FL	*- FL
53	1	*REAR NUMBER PLATE WITH PLATE	Not Necessary	70.00 FS	*- FS
54	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
55	1	*SET REAR BUMPER BOTTOM CENTER GARNISH	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	1	*SET REAR BUMPER LOWER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
57	1	*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
58	1	*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
59	1	*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
60	1	*BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
61	1	*SET BOOTLID NUMBER PLATE LAMP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
62	2	*SET TAILLAMP CLIP	Necessary	60.00 FS	*20.00 FS
63	2	*TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
64	2	*REAR FENDER SEALANT	Not Necessary	300.00 FS	*- FS
65	1	*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
66	1	*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
67	1	*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
68	1	*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
69	1	*REAR WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
70	1	*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
71	1	*SET REAR END PANEL INNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
72	1	*REAR FLOOR PANEL (WELL PANEL) SEALANT	Not Necessary	350.00 FS	*- FS
73	1	*SET REAR FLOOR UNDER SIDE GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,792.00	7,863.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,675.20	779.31
Total Parts (\$\$)	35,116.80	7,083.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	700.00
3	TUFF COAT	New	200.00	80.00
4	WIRING CHECK ON TAILAMP	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	380.00	80.00
6	TRANSFER BOOTLID MECHANISM	New	80.00	80.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX AND RESET BOOTLID AUTO SYSTEM	New	250.00	0.00
9	REMOVE AND REFIX REAR FLOOR PANEL (WELL PANEL)	New	350.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
11	REAR CHASSIS ALIGNMENT	New	250.00	0.00
12	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (S\$)			6,410.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >