

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007257/APA3Q2**Date:** 01/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070028076
Claimant Vehicle No :	SME6205G	Insured Vehicle No :	GBE7856B
Date of Loss:	27/07/2022	Nature of Claim:	TP
		Claim No:	5429051091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6205G		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0B90024
Reg. Date:	09/10/2018 (Man. Year: 2018)	Chassis No:	ZWR800329763
Colour:	Black	Odometer:	265298 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,518.09	12,389.22	10,128.87	44.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,670.00	3,280.00	3,390.00	50.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,188.09	15,669.22	13,518.87	46.32
Approved Total (Overridden) (S\$)		12,500.00		
Nett Amount (S\$)	29,188.09	12,500.00	16,688.09	57.17
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,307.45		

INSPECTION

Date of Assignment:	27/07/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	27/07/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	11.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,339.31 FL	*1,025.00 FL
2	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.10 FL	*- FL
3	1		*REAR BUMPER REFLECTOR	O/S Cracked	251.20 FL	*125.60 FL
4	1		*REAR BUMPER SIDE RETAINER (FRONT)	O/S Damaged	291.60 FL	*145.80 FL
5	1		*TAILGATE	Dented	1,812.70 FL	*1,812.70 FL
6	1		*TAILGATE OUTER MOULDING	Cut	762.80 FL	*581.00 FL
7	1		*TAIL GATE LOGO	Necessary	78.00 FL	*78.00 FL
8	1		*TAIL GATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	58.20 FL	*58.20 FL
9	2		*TAILGATE STOPPER RH	Not Necessary	57.20 FL	*- FL
10	1		*TAILGATE LOWER LOCK	Not Necessary	36.70 FL	*- FL
11	2		*TAILGATE DAMPER	Not Necessary	653.60 FL	*- FL
12	2		*TAILGATE HINGE	Not Necessary	226.80 FL	*- FL
13	1		*TAILGATE DETECTOR WIRE HARNESS	Not Necessary	287.10 FL	*- FL
14	1		*TAILGATE TOP TRIM	Cut	385.00 FL	*385.00 FL
15	1		*TAILGATE INNER TRIM	Deformed	850.00 FL	*850.00 FL
16	1		*TAILGATE SIDE TRIM	O/S Deformed	920.20 FL	*385.00 FL
17	1		*TAILGATE WEATHERSTRIP	Cut	375.10 FL	*375.10 FL
18	1		*TAILGATE WINDSCREEN GLASS C/W MOULDING	Shattered	2,810.00 FL	*1,450.00 FL
19	1		*TAIL LAMP RH	Cracked	685.10 FL	*685.10 FL
20	1		*TAIL LAMP OUTER PANEL RH	Repair	311.10 FL	*- FL
21	1		*TAIL LAMP OUTER LOWER PANEL RH	Dented	288.50 FL	*288.50 FL
22	1		*TAIL LAMP INNER PANEL RH	Repair	398.10 FL	*- FL
23	1		*TAIL LAMP INNER LOWER PANEL RH	Repair	376.20 FL	*- FL
24	1		*TAIL LAMP LOWER GARNISH RH	Deformed	178.80 FL	*178.80 FL
25	2		*TAIL LAMP LOWER GARNISH RETAINER	Not Necessary	321.40 FL	*- FL
26	1		*REAR FENDER RH	Buckled	1,876.50 FL	*1,340.00 FL
27	1		*REAR FENDER GLASS C/W MOULDING RH	Necessary	598.70 FL	*158.00 FL
28	1		*REAR FENDER RAILWAY RH	Not Necessary	286.00 FL	*- FL
29	1		*REAR FENDER RAILWAY COVER GARNISH RH	Cracked	316.10 FL	*316.10 FL
30	1		*REAR FENDER INNER PANEL RH	Repair	1,251.00 FL	*- FL
31	1		*REAR FENDER INNER UPPER TRIM RH	Cracked	421.10 FL	*421.10 FL
32	1		*REAR FENDER INNER TRIM RH	Cracked	906.51 FL	*781.00 FL
33	2		*REAR FENDER COWLING	Torn	221.60 FL	*221.60 FL
34	1		*REAR AIR CON BLOWER MOTOR	Cracked	3,694.00 FL	*2,255.00 FL
35	1		*REAR END PANEL C/W END EXTEND PANEL	Dented	735.70 FL	*735.70 FL
36	1		*REAR END PANEL TOP GARNISH	Not Necessary	148.60 FL	*- FL
37	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	1,105.50 FL	*- FL
38	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
40	1		*REAR BUMPER REFLECTOR STICKER (SPECAIL TYPE)	Necessary	120.00 FS	*50.00 FS
41	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*10.00 FS
42	1		*SET TAIL LAMP LOWER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
43	2		*TAIL LAMP INNER LOWER PANEL SEALANT	Necessary	160.00 FS	*30.00 FS
44	1		*SET TAILGATE OUTER MOULDING CLIP	Necessary	40.00 FS	*10.00 FS
45	1		*SET TAILGATE INNER TRM CLIP	Necessary	80.00 FS	*30.00 FS
46	1		*SET TAILGATE TOP INNER TRIM CLIP	Necessary	50.00 FS	*10.00 FS
47	1		*SET TAILGATE SIDE INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
48	1		*TAILGATE SIDE SEAL (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
49	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
50	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
51	1		*TAILGATE WINDSCREEN SOLAR FILM	Necessary	120.00 FS	*120.00 FS
52	1		*REAR FENDER RH SEALANT	Necessary	150.00 FS	*50.00 FS
53	1		*REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
54	1		*REAR FENDER GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
55	1		*REAR FENDER GLASS SOLAR FILM	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
57	1		*SET REAR FENDER INNER COWLING CLIP	Necessary	80.00 FS	*10.00 FS
58	1		*SET REAR FENDER RAILWAY COVER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
59	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
60	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
61	1		*PRIVATE HIRE DECAL	Necessary	80.00 FS	*40.00 FS
62	1		*VIDEO RECORDER	Missing	850.00 FS	*580.00 FS
63	2		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,854.12	16,052.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,336.03	3,663.08
Total Parts (\$\$)	22,518.09	12,389.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,800.00	1,300.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	250.00	100.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	180.00	80.00
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR	New	350.00	200.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX SILDING DOOR AND RESET AUTO SYSTEM	New	250.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
12	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
13	REMOVE AND REFIX REAR FENDER GLASS RH	New	120.00	50.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			6,670.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >