

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16016456/M1PA3Q2-1
Date: 05/08/2022

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1693215
Claimant Vehicle No :	SHB6335P	Insured Vehicle No :	YE2888U
Date of Loss:	29/08/2016	Nature of Claim:	TP
		Claim No:	C0398006

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6335P	Engine No:	D4FDDU349515
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMDU039869
Reg. Date:	30/09/2013 (Man. Year: 2013)	Odometer:	475307 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	73,160.51	52,886.91	20,273.60	27.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,750.00	6,900.00	2,850.00	29.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,910.51	59,786.91	23,123.60	27.89
Approved Total (Overridden) (S\$)		20,000.00		
(S\$)	82,910.51	20,000.00	62,910.51	75.88
+ GST 7.00/7.00% (S\$)	5,803.74	1,400.00	4,403.74	75.88
Nett Amount (S\$)	88,714.25	21,400.00	67,314.25	75.88
+ Loss of Use (20.0 x S\$50.00/day) (S\$)		1,000.00		
+ Car Rental (20.0 x S\$130.54/day) (S\$)		2,610.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		25,012.80		
Global Sum Settlement (S\$)		25,000.00		

INSPECTION

Date of Assignment:	01/09/2016	Chunni Motor Work Pte Ltd (HQ)
Date Inspected:	02/09/2016 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Estimated Period of Repair:	20.0 days	Singapore 568047

Adjuster: MA CHIN FOOK

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6335P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (CONSISTENT)	Buckled	1,526.00 FL	*1,526.00 FL
2	1		*BONNET LOCK (CONSISTENT)	Bent	50.90 FL	*50.90 FL
3	1		*BONNET INSULATOR (CONSISTENT)	Distorted	243.00 FL	*243.00 FL
4	1		*BONNET INSULATOR CLIPS (CONSISTENT)	Necessary	8.40 FL	*8.40 FL
5	1		*RADIATOR GRILLE (CONSISTENT)	Distorted	1,480.00 FL	*1,480.00 FL
6	1		*RADIATOR GRILLE H EMBLEM (CONSISTENT)	Necessary	290.80 FL	*290.80 FL
7	1		*RADIATOR GRILLE CHROME MOULDING (CONSISTENT)	Distorted	395.50 FL	*395.50 FL
8	1		*FRONT BUMPER COVER (CONSISTENT)	Deformed	1,052.20 FL	*1,052.20 FL
9	1		*FRONT BUMPER SPONGE (CONSISTENT)	Torn	142.20 FL	*142.20 FL
10	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	526.10 FL	*526.10 FL
11	1		*FRONT BUMPER REINFORCEMENT BAR (CONSISTENT)	Bent	258.50 FL	*258.50 FL
12	1		*FRONT BUMPER GRILLE (LH) (CONSISTENT)	Distorted	285.50 FL	*285.50 FL
13	1		*FRONT BUMPER GRILLE AIRDUCT (LH) (CONSISTENT)	Distorted	155.00 FL	*155.00 FL
14	1		*FRONT BUMPER BRACKET TOP (LH) (CONSISTENT)	Distorted	22.40 FL	*22.40 FL
15	1		*FRONT BUMPER BRACKET (LH) (CONSISTENT)	Distorted	24.60 FL	*24.60 FL
16	1		*FRONT BUMPER RETAINER MOUNTING (CONSISTENT)	Distorted	9.20 FL	*9.20 FL
17	1		*HEADLAMP SUPPORT TOP COVER (CONSISTENT)	Distorted	398.00 FL	*398.00 FL
18	1		*HEADLAMP SUPPORT PANEL ASSY (CONSISTENT)	Bent	1,067.50 FL	*1,067.50 FL
19	2		*HEADLAMP (LH/RH) (CONSISTENT)	Cracked	2,776.00 FL	*2,776.00 FL
20	1		*RADIATOR (CONSISTENT)	Bent	850.20 FL	*850.20 FL
21	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY (CONSISTENT)	Distorted	792.95 FL	*792.95 FL
22	2		*RADIATOR BRACKET (RH/LH) (CONSISTENT)	Distorted	13.00 FL	*13.00 FL
23	1		*RADIATOR HOSE UPPER (CONSISTENT)	Distorted	47.40 FL	*47.40 FL
24	1		*RADIATOR HOSE LOWER (CONSISTENT)	Serviceable	47.40 FL	*- FL
25	1		*RADIATOR EXPANSION TANK (CONSISTENT)	Serviceable	48.00 FL	*- FL
26	2		*RADIATOR GUARD (CONSISTENT)	Distorted	70.00 FL	*70.00 FL
27	2		*HORN UNIT (LH/RH) (CONSISTENT)	Distorted	173.50 FL	*173.50 FL
28	1		*HORN WIRE (CONSISTENT)	Serviceable	156.50 FL	*- FL
29	1		*FRONT FENDER (LH) (CONSISTENT)	Buckled	619.00 FL	*619.00 FL
30	1		*FRONT FENDER APRON PANEL (LH) (CONSISTENT)	Bent	1,575.50 FL	*1,575.50 FL
31	1		*FRONT FENDER SHIELD (LH) (CONSISTENT)	Distorted	169.80 FL	*169.80 FL
32	1		*FRONT FENDER RETAINER (CONSISTENT)	Distorted	9.20 FL	*9.20 FL
33	1		*AIR CLEANER ASSY (CONSISTENT)	Distorted	128.40 FL	*128.40 FL
34	1		*AIR DUCT (CONSISTENT)	Distorted	206.05 FL	*206.05 FL
35	1		*AIR CLEANER BODY (CONSISTENT)	Repair	106.20 FL	*- FL
36	1		*AIRCON CONDENSER (CONSISTENT)	Bent	1,137.35 FL	*1,137.35 FL
37	1		*FRONT WINDSCREEN GALSS (CONSISTENT)	Cracked	1,059.25 FL	*1,059.25 FL
38	1		*FRONT WINDSCREEN MOULDING (CONSISTENT)	Necessary	60.00 FL	*60.00 FL
39	1		*FRONT WHEEL RIM (LH) (CONSISTENT)	Serviceable	351.90 FL	*- FL
40	1		*FRONT WHEEL HUB CAP (LH) (CONSISTENT)	Serviceable	158.90 FL	*- FL
41	1		*FRONT WHEEL BEARING (CONSISTENT)	Serviceable	258.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT SHOCK ABSORBER (ASSY) (LH) (CONSISTENT)	Serviceable	342.20 FL	*- FL
43	1		*FRONT SHOCK ABSORBER MOUNTING (LH) (CONSISTENT)	Serviceable	75.10 FL	*- FL
44	1		*FRONT DRIVE SHAFT (LH) (CONSISTENT)	Serviceable	1,069.55 FL	*- FL
45	1		*RACK & PINION ASSY (CONSISTENT)	Serviceable	2,184.00 FL	*- FL
46	1		*STG TIE ROD (CONSISTENT)	Serviceable	162.00 FL	*- FL
47	1		*STG TIE END (CONSISTENT)	Serviceable	69.50 FL	*- FL
48	1		*STABILIZER BAR (CONSISTENT)	Serviceable	252.30 FL	*- FL
49	1		*STABILIZER BAR BUSH (LH) (CONSISTENT)	Serviceable	14.20 FL	*- FL
50	1		*STABILIZER BAR LINK (CONSISTENT)	Serviceable	81.70 FL	*- FL
51	1		*STABILIZER BRACKET (CONSISTENT)	Serviceable	24.00 FL	*- FL
52	1		*FRONT SUSPENSION LOWER ARM (LH) (CONSISTENT)	Bent	715.10 FL	*715.10 FL
53	1		*KNUCKLE ARM (LH) (CONSISTENT)	Bent	582.95 FL	*582.95 FL
54	1		*ENGINE MOUNTING (CONSISTENT)	Serviceable	481.90 FL	*- FL
55	1		*ENGINE UNDER COVER (CONSISTENT)	Serviceable	343.10 FL	*- FL
56	1		*ENGINE CROSSMEMBER (CONSISTENT)	Serviceable	2,236.90 FL	*- FL
57	1		*ENGINE MTG (FRONT) (CONSISTENT)	Serviceable	235.30 FL	*- FL
58	1		*ENGINE MTG (REAR) (CONSISTENT)	Serviceable	279.60 FL	*- FL
59	1		*GEARBOX (CONSISTENT)	Jammed	14,808.00 FL	*14,808.00 FL
60	1		*GEARBOX MOUNTING (CONSISTENT)	Serviceable	342.50 FL	*- FL
61	1		*INTER COOLER (CONSISTENT)	Bent	921.90 FL	*921.90 FL
62	2		*INTER COOLER MOUNTING (CONSISTENT)	Distorted	25.90 FL	*25.90 FL
63	1		*HOSE B TO INTER COOLER (CONSISTENT)	Distorted	229.70 FL	*229.70 FL
64	1		*HOSE C TO INTER COOLER INLET (CONSISTENT)	Serviceable	113.30 FL	*- FL
65	1		*ABS SENSOR (CONSISTENT)	Serviceable	261.50 FL	*- FL
66	1		*WIRING-ENGINE (CONSISTENT)	Distorted	3,326.00 FL	*3,326.00 FL
67	1		*WIRING-FRONT (CONSISTENT)	Distorted	1,960.80 FL	*1,960.80 FL
68	1		*AIRBAG COMPLETE (CONSISTENT)	Activated	2,948.50 FL	*2,948.50 FL
69	1		*AIRBAG CONTROL MODULE (CONSISTENT)	Activated	1,894.00 FL	*1,894.00 FL
70	1		*STEERING ANGLE ASSY (CONSISTENT)	Activated	1,150.60 FL	*1,150.60 FL
71	1		*SENSOR ASSY IMPACT - FRT INPACT (CONSISTENT)	Necessary	1,180.50 FL	*1,180.50 FL
72	2		*AIRBAG SENSOR (CONSISTENT)	Serviceable	1,160.00 FL	*- FL
73	1		*ELECTRIC POWER STEERING (CONSISTENT)	Serviceable	4,880.50 FL	*- FL
74	1		*FRONT CUSHION SEAT (RH) (CONSISTENT)	Bent	4,793.60 FS	*1,500.00 FS
75	1		*FRONT NUMBER PLATE (CONSISTENT) }	Distorted	25.00 FS	*40.00 FS
76	1		*FRONT NO PLATE TRIM COVER (CONSISTENT) }		30.00 FS	*- FS
77	1		*FRONT TYRE (LH) (80%) (CONSISTENT)	Punctured	216.00 FS	*172.80 FS
78	1		*FRONT WINDSCREEN SEALANT (CONSISTENT)	Necessary	46.00 FS	*46.00 FS
79	1		*BOOT LID (CONSISTENT)	Bent	1,681.40 FL	*1,681.40 FL
80	1		*BOOT LID RUBBER (CONSISTENT)	Distorted	115.80 FL	*115.80 FL
81	1		*BOOT LID LOCK UPPER (CONSISTENT)	Bent	137.90 FL	*137.90 FL
82	1		*BOOT LID LOCK LOWER (CONSISTENT)	Bent	31.70 FL	*31.70 FL
83	1		*BOOT LID H EMBLEM (CONSISTENT)	Necessary	27.20 FL	*27.20 FL
84	1		*BOOT LID CRDI PLATE (CONSISTENT)	Necessary	41.00 FL	*41.00 FL
85	2		*BOOT LID LAMP (LH/RH) (CONSISTENT)	Cracked	1,113.60 FL	*1,113.60 FL
86	2		*LICENCE LAMP (LH/RH) (CONSISTENT)	Cracked	67.90 FL	*67.90 FL
87	1		*BOOT LID TRIMBOARD (CONSISTENT)	Distorted	172.70 FL	*172.70 FL
88	11		*BOOT LID TRIMBOARD CLIPS (CONSISTENT)	Necessary	11.00 FL	*11.00 FL
89	1		*BOOTLID MOULDING (CONSISTENT)	Distorted	85.00 FL	*85.00 FL
90	1		*BOOTLID I40 EMBLEM (CONSISTENT)	Necessary	41.00 FL	*41.00 FL
91	1		*BOOTLID LOWER GARNISH (CONSISTENT)	Distorted	398.00 FL	*398.00 FL
92	1		*REAR BUMPER (CONSISTENT)	Deformed	33.96 FL	*33.96 FL
93	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	504.35 FL	*504.35 FL
94	2		*REAR BUMPER REINFORCEMENT BRACKET (CONSISTENT)	Bent	360.00 FL	*360.00 FL
95	2		*REAR BUMPER SIDE BRACKET (CONSISTENT)	Distorted	98.00 FL	*98.00 FL
96	1		*REAR BUMPER SPONGE (CONSISTENT)	Torn	143.40 FL	*143.40 FL
97	1		*REAR BUMPER UNDER COVER (CONSISTENT)	Distorted	225.80 FL	*225.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*REAR BUMPER REFLECTOR LAMP (LH/RH) (CONSISTENT)	O/s Serviceable / N/s Cracked	64.00 FL	*32.00 FL
99	2		*TAIL LAMP (LH/RH) (CONSISTENT)	Cracked	1,131.20 FL	*1,131.20 FL
100	1		*TAIL LAMP QUARTER PANEL (LH/RH) (CONSISTENT)	N/s Bent / O/s Repair	195.80 FL	*97.90 FL
101	1		*REAR PANEL (CONSISTENT)	Bent	592.30 FL	*592.30 FL
102	1		*REAR PANEL GARNISH (CONSISTENT)	Distorted	57.70 FL	*57.70 FL
103	1		*REAR PANEL LOWER PANEL (CONSISTENT)	Bent	495.50 FL	*495.50 FL
104	1		*SPARE TYRE HOLDER (CONSISTENT)	Serviceable	143.40 FL	*- FL
105	1		*TAIL LAMP PANEL TOP (LH) (CONSISTENT)	Bent	545.90 FL	*545.90 FL
106	1		*SPARE TYRE PANEL (CONSISTENT)	Bent	900.50 FL	*900.50 FL
107	1		*SPARE TYRE PANEL CUSHION (CONSISTENT)	Serviceable	209.05 FL	*- FL
108	1		*REAR TOWING HOOK (CONSISTENT)	Serviceable	94.60 FL	*- FL
109	1		*MEMBER ASSY - REAR FLOOR CENTRE (CONSISTENT)	Repair	170.75 FL	*- FL
110	2		*EXHAUST PIPE INSULATOR (CONSISTENT)	Serviceable	117.10 FL	*- FL
111	2		*EXHAUST SILENCER (CONSISTENT)	Serviceable	1,908.00 FL	*- FL
112	1		*EXHAUST PIPE HANGER (CONSISTENT)	Serviceable	117.10 FL	*- FL
113	1		*EXHAUST PIPE CENTRE (CONSISTENT)	Serviceable	1,150.30 FL	*- FL
114	1		*REAR FENDER WITH HOUSING (LH) (CONSISTENT)	Bent	4,736.80 FL	*4,736.80 FL
115	1		*REAR FENDER INNER LINING (LH) (CONSISTENT)	Serviceable	164.40 FL	*- FL
116	1		*REAR FENDER AIR-DUCT (CONSISTENT)	Serviceable	225.60 FL	*- FL
117	1		*REAR FENDER TRIM BOARD (LH) (CONSISTENT)	Distorted	188.75 FL	*188.75 FL
118	1		*REAR WINDSCREEN GLASS (CONSISTENT)	Serviceable	985.50 FL	*- FL
119	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	62.15 FL	*62.15 FL
120	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
121	1		*REAR NO. PLATE (CONSISTENT)	Distorted	25.00 FS	*25.00 FS
122	1		*REAR BUMPER REVERSE SENSOR (CONSISTENT)	Shorted	135.70 FS	*135.70 FS
123	1		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	46.00 FS	*46.00 FS
124	2		*FRT SAFETY BELT (ASSY) (LH/RH) (CONSISTENT)	Activated	1,145.30 FL	*1,145.30 FL
125	2		*FRT SEAT BELT ADJUSTER (LH/RH) (CONSISTENT)	Bent	971.20 FL	*971.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	90,113.81	65,609.76
- List Item Discount on L Items 20.00/20.00% (\$)	16,953.30	12,722.85
Total Parts (\$)	73,160.51	52,886.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	4,000.00	2,800.00
2	SPRAY PAINTING CHARGE.	New	2,200.00	1,920.00
3	WIRING CHARGE.	New	150.00	60.00
4	TUFF KOTE.	New	150.00	110.00
5	TOWING CHARGE.	New	50.00	50.00
6	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	180.00
7	FRT WHEEL ALIGNMENT.	New	120.00	80.00
8	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	100.00
9	REMOVE / REFIX GEARBOX.	New	450.00	350.00
10	REMOVE / REFIX DASHBOARD.	New	450.00	280.00
11	REMOVE / REFIX FUSE BOX.	New	180.00	120.00
12	REMOVE / REFIX FRONT WINDSCREEN GLASS.	New	120.00	100.00
13	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.	New	90.00	60.00
14	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM.	New	550.00	350.00
15	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
16	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	100.00
17	REMOVE / REFIX REVERSE SENSOR.	New	120.00	60.00
18	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
19	REMOVE / REFIX EXHAUST PIPE.	New	150.00	100.00
Gross Labour Cost (\$\$)			9,750.00	6,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >