



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 6899U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED/TORN	796.80	581.10
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT RH BUMPER BRACKET	CRACKED	178.00	151.80
1	FRONT RH HEAD LAMP	SCRATCHED	704.10	704.10
1	FRONT RH DOOR	TO REPAIR SEE LABOUR	1,568.30	-
	LESS 25% DISCOUNT		-	-371.75
			3,297.20	1,115.25
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT RH HEAD LAMP CLIP (SN)	NOT NECESSARY	65.00	-
			65.00	-
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		40.00	20.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	200.00
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	50.00	-
	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS.	NOT NECESSARY	80.00	-
			1,370.00	520.00
	GRAND TOTAL		4,732.20	1,635.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00
---	--	--	-----------------

Report Ref No. CS/AGI22007279/Uvc4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.