

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22007283/ACY3Q2**Date:** 12/01/2023REFERENCE

Insured/Claimant: TAN TUANG JOO LESLIE Policy No: SP2000702593
Date of Loss: 27/07/2022 Nature of Claim: OD Claim No: 202222005868JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFM7733H**
Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NR8923088
Reg. Date: 29/01/2021 (Man. Year: 2019) Chassis No: NSP1707199502
Colour: White Odometer: 20169 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$103,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,648.50	4,528.70	1,119.80	19.82
Miscellaneous Items	250.00	200.00	50.00	20.00
Labour	1,060.00	940.00	120.00	11.32
Paintwork Labour	1,100.00	800.00	300.00	27.27
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,058.50	6,468.70	1,589.80	19.73
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	8,058.50	5,868.70	2,189.80	27.17
+ GST 7.00/7.00% (S\$)	564.10	410.81	153.29	27.17
Nett Amount (S\$)	8,622.60	6,279.51	2,343.09	27.17

INSPECTION

Date of Assignment: 30/07/2022 Present Location: Kan Fook Sing Motor Workshop (Defu)
Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 01/08/2022 Inspected At: Blk 8 Defu South Street 1, Defu Industrial City #04-29
Singapore 533758
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFM7733H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cracked	310.00 F	*300.00 F
2	1		*FRONT HEADLAMP TOP PANEL RH	Not Necessary	40.00 F	*- F
3	1		*FRONT FENDER RH	Distorted	155.00 F	*160.00 F
4	1		*FRONT FENDER SHIELD RH	Torn	80.00 F	*75.00 F
5	10		*FRONT FENDER SHIELD CLIP	Necessary	25.00 F	*25.00 F
6	1		*FRONT FENDER 1/4 GARNISH RH	Not Necessary	45.00 F	*- F
7	1		*FRONT BUMPER	Distorted	170.00 F	*150.00 F
8	1		*FRONT BUMPER SIDE RETAINER RH	Missing	30.00 F	*25.00 F
9	1		*FRONTBUMPER FOGLAMP COVER RH	Missing	45.00 F	*60.00 F
10	1		*FRONT BUMPER LOWER COVER	Not Necessary	60.00 F	*- F
11	10		*FRONT BUMPER CLIP	Necessary	25.00 F	*12.00 F
12	1		*FRONT DOOR RH	Dented	450.00 F	*390.00 F
13	1		*FRONT DOOR HINGE TOP RH	Not Necessary	40.00 F	*- F
14	1		*FRONT DOOR HINGE LOWER RH	Not Necessary	40.00 F	*- F
15	1		*FRONT DOOR CHECKER RH	Not Necessary	65.00 F	*- F
16	1		*FRONT SHOCK ABSORBER RH	Bent	185.00 F	*185.00 F
17	1		*FRONT SHOCK ABSORBER MOUNTING RH	Not Necessary	55.00 F	*- F
18	1		*FRONT LOWER ARM RH	Bent	210.00 F	*210.00 F
19	1		*FRONT KNUCKLE ARM RH	Damaged	150.00 F	*150.00 F
20	1		*FRONT KNUCKLE BEARING RH	Damaged	50.00 F	*50.00 F
21	1		*FRONT STABILZIER LINK RH	Bent	60.00 F	*60.00 F
22	1		*FRONT DRIVE SHAFT RH	Damaged	585.00 F	*585.00 F
23	1		*STEERING RACK AND PINION	Not Necessary	580.00 F	*- F
24	1		*STEERING TIE ROD END RH	Bent	40.00 F	*40.00 F
25	1		*FRONT WHEEL RIM RH	Distorted	150.00 F	*150.00 F
26	1		*FRONT HUP CAP RH	Missing	110.00 F	*110.00 F
Supplementary #1						
27	1		*FRONT CROSS MEMBER ASSY	Bent	750.00 F	*750.00 F
28	1		*FRONT WHEEL BEARING HUB RH	Damaged	110.00 F	*110.00 F
29	1		*FRONT BRAKE CALLIPER RH	Damaged	260.00 F	*260.00 F
30	10		*FRONT DOOR RIVET	Necessary	15.00 F	*15.00 F
31	1		*FRONT SPEED SENSOR RH	Damaged	150.00 F	*150.00 F
32	1		*FRONT BONNET CABLE	Damaged	30.00 F	*30.00 F
33	1		*FRONT BRAKE DISC ROTOR COVER	Distorted	65.00 F	*65.00 F

F=Franchise part.

Sub Total (S\$)	5,135.00	4,117.00
+ Margin on L,N Items 10.00/10.00% (S\$)	513.50	411.70
Total Parts (S\$)	5,648.50	4,528.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT TYRE RH (Punctured)	250.00	200.00
Sub Total (\$\$)			250.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,100.00	800.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	TO CHECK ALIGNMENT	New	100.00	80.00
4	TO REMOVE/REFIT FRONT UNDERCARRIAGE RH	New	180.00	180.00
5	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	50.00	50.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	680.00	600.00
Gross Labour Cost (\$\$)			2,160.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >