



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|--|
| LOH CHEE GUAN FRANCIS | Cust No/Name /LOH CHEE GUAN FRANCIS |
| BLK 216 JURONG EAST ST 21 | Reg No/Reg Date SMG1343M / 05/12/201 |
| #04-503 | Date In/Mileage 25/07/2022/ 0 |
| SINGAPORE 600216 | Chassis No KNAF3416MK5021653 |
| Contact No Mobile: 98502101 | Engine No G4FGJH709934 |
| | Make/Model KIA/CERATO 1.6 A SR SX G335 |
| | Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|--|-------|-------------------|-----|-------------------|--------|------------|-------|---------|
| CSM00081 | Cash | 25/07/2022/ 09:27 | BLK | 282 / Kevin Leong | 54839 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 1920.00 |
| REPLACE FRT BUMPER, FRT LH FENDER & AFFECTED AREA | | | | | | | | |
| E PNT98000 | | | | | | | | 1650.00 |
| PAINT WORK ON FTR BUMPER & FRT LH FENDER | | | | | | | | |
| M SUNDRY | | | | | | | | 100.00 |
| PERFORM RUST PREVENTION | | | | | | | | |
| M SUNDRY | | | | | | | | 50.00 |
| TO APPLY SEALANT OPN AFFECTED AREA | | | | | | | | |
| A 54900099 | | | | | | | | 150.00 |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | | |
| A 10028901 | | | | | | | | 280.00 |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | | |
| E PNT88000 | | | | | | | | 120.00 |
| REMOVE & INSTALL FRT PARKING ASSISTS | | | | | | | | |
| M SUNDRY | | | | | | | | 50.00 |
| SUNDRIES | | | | | | | | |
| M LAMP ASSY-HEAD,LH | | | | | 1.00 | 2210.00 | 00.00 | 2210.00 |
| M PANEL-FENDER,LH | | | | | 1.00 | 593.00 | 00.00 | 593.00 |
| M GUARD ASSY-FRONT WHEEL,LH | | | | | 1.00 | 95.00 | 00.00 | 95.00 |
| M COVER-FR BUMPER | | | | | 1.00 | 633.00 | 00.00 | 633.00 |
| M GRILLE-FRONT BUMPER | | | | | 1.00 | 485.00 | 00.00 | 485.00 |
| M MOULDING-FRONT BUMPER,LH | | | | | 1.00 | 216.00 | 00.00 | 216.00 |
| M LAMP ASSY-SIDE REPEATER,LH | | | | | 1.00 | 164.00 | 00.00 | 164.00 |
| M AIR DUCT-FR BUMPER,LH | | | | | 1.00 | 14.00 | 00.00 | 14.00 |
| M BRACKET-FR BUMPER UPR SIDE MTG | | | | | 1.00 | 22.00 | 00.00 | 22.00 |
| M ULTRASONIC SENSOR ASSY-P.A.S | | | | | 1.00 | 163.00 | 00.00 | 163.00 |

Confirm & accepted by

| | | |
|----------------------|-------------|-----------------|
| | Nett | 8,915.00 |
| 7% GST on | 8915.00 | 624.05 |
| Total Payable | | 9,539.05 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.