

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22007291/AYA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000692281
Claimant Vehicle No :	SLW5729K	Insured Vehicle No :	SLK1281Z
Date of Loss:	29/07/2022	Nature of Claim:	TP
		Claim No:	202222005887

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW5729K	Engine No:	LEB6321536
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71117466
Reg. Date:	22/02/2018 (Man. Year: 2017)	Odometer:	153305 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,535.36	1,746.64	1,788.72	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	980.00	450.00	31.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,965.36	2,726.64	2,238.72	45.09
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	4,965.36	2,000.00	2,965.36	59.72
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,247.45		

INSPECTION

Date of Assignment:	01/08/2022	
Date Inspected:	03/08/2022	Inspected At: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 May 2023)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW5729K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,036.16 FS	*200.00 FS
2	1		*TAIL GATE LOCK	Damaged	96.60 FL	*96.60 FL
3	1		*TAIL GATE LOWER CATCH	Not Necessary	24.70 FL	*- FL
4	1		*TAIL GATE WEATHERSTRIP	Not Necessary	168.50 FL	*- FL
5	1		*TAIL GATE TRIMBOARD	Not Necessary	320.80 FL	*- FL
6	1		*TAIL GATE H LOGO	Not Necessary	38.20 FL	*- FL
7	1		*TAIL GATE SHUTTLE EMBLEM	Necessary	55.20 FL	*55.20 FL
8	1		*TAIL GATE HYBRID EMBLEM	Necessary	88.00 FL	*88.00 FL
9	1		*REAR BUMPER	Deformed	1,180.40 FL	*1,050.00 FL
10	1		*REAR BUMPER SIDE RETAINER RH	Necessary	26.50 FL	*26.50 FL
11	1		*REAR BUMPER SIDE RETAINER LH	Necessary	26.50 FL	*26.50 FL
12	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	26.50 FL	*- FL
13	1		*REAR BUMPER REFLECTOR GARNISH RH	Not Necessary	45.20 FL	*- FL
14	1		*REAR BUMPER REFLECTOR GARNISH LH	Not Necessary	45.20 FL	*- FL
15	1		*REAR BUMPER REFLECTOR LH	Not Necessary	45.60 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Not Necessary	45.60 FL	*- FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	228.00 FL	*228.00 FL
18	1		*REAR NUMBER PLATE W/CASING	Not Necessary	70.00 FS	*- FS
19	1		*SEALANT	Necessary	80.00 FS	*60.00 FS
20	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	16		*TAIL GATE TRIMBOARD CLIP	Not Necessary	80.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
Sub Total (\$\$)					4,027.66	2,060.80
- List Item Discount on L Items 20.00/20.00% (\$\$)					492.30	314.16
Total Parts (\$\$)					3,535.36	1,746.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	600.00	400.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	600.00	400.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	50.00	30.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
Gross Labour Cost (\$\$)			1,430.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >