

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9427R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR N/S	DENTED / WARPED	1,120.20	981.20
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,188.10	-
1	REAR BUMPER	CUT	1,071.90	936.00
1	REAR BUMPER SIDE RETAINER N/S	NOT NECESSARY	45.00	-
1	REAR WHEEL HUB BEARING N/S	NOT NECESSARY	650.00	-
	LESS 20% DISCOUNT		-	-383.44
			4,075.20	1,533.76
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
1	REAR SPORT RIM N/S (SN)	WARPED	650.00	450.00
1	SET REAR DOOR FRAME BLACK STICKER N/S (SN)	NECESSARY	60.00	60.00
1	REAR DOOR VISOR N/S (SN)	NECESSARY	50.00	50.00
			800.00	600.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO TRANSFER REAR DOOR MECHANISM.		80.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	TO DISMANTLE & REFIX REAR UNDER CARRIAGE.	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		800.00	350.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	600.00
			2,610.00	1,140.00
	GRAND TOTAL		7,485.20	3,273.76



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,600.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO22007298/Uqce2

CHUA KANG SENG

Licensed Appraiser