

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO22007301/Ancq2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	16/11/2022	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGZ 7778Z	Veh. Inspected	SJP 5636E	
	Policy No.	D22MTPV01010191	Coverage (\$)	0.00	
	Claim No.	CMTD2202595/THE	Excess (\$)	0.00	
	Assign From		Assign Date	01/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	KMHDU41BR9U712943	Colour	RED	
	Odometer	104106 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	WEST LAKE	6 mm	
	L/H Front Tyre	185/65 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	185/65 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	185/65 R15	WEST LAKE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/07/2022	Inspection Date	02/08/2022	
	Survey held at	AP AUTOMOTIVE SERVICES P	TE LTD		
		9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				