

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22007304/KVY3M4**Date:** 14/09/2022**REFERENCE**

Insured/Claimant: BIS MOTORING PTE LTD Policy No: MCF22A00000100
Date of Loss: 29/07/2022 Nature of Claim: OD Claim No: DMCF2200156H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE2810Z**
Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D060176
Reg. Date: 01/03/2022 (Man. Year: 2019) Chassis No: VF1RFA00063211961
Colour: Metallic Red Odometer: 53431 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$127,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20
Front Left Side: Davanti 7 mm Rear Left Side: Continental 6 mm
Front Right Side: Davanti 7 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,410.56	7,852.66	13,557.90	63.32
Miscellaneous Items	87.00	42.00	45.00	51.72
Labour	2,830.00	1,100.00	1,730.00	61.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,327.56	8,994.66	15,332.90	63.03
Approved Total (Overridden) (S\$)		5,700.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	22,327.56	3,700.00	18,627.56	83.43
+ GST 7.00/7.00% (S\$)	1,562.93	259.00	1,303.93	83.43
Nett Amount (S\$)	23,890.49	3,959.00	19,931.49	83.43

INSPECTION

Date of Assignment: 01/08/2022 Present Location: Munich Autocare Pte Ltd (HQ)
Date Inspected: 02/08/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days 60 Jalan Lam Huat, #07-43
Singapore 737869

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Sep 2022)

Parts: M1-MPV RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE2810Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*651004703R FRONT BONNET (WCP)	Bent	1,509.76 F	*1,348.00 F
2	1		*656016673R BONNET LOCK (WCP)	Distorted	208.32 F	*208.32 F
3	1		*654000247R FRONT BONNET HINGE RH (WCP)	Distorted	150.41 F	*150.41 F
4	1		*654013594R FRONT BONNET HINGE LH (WCP)	Distorted	150.41 F	*150.41 F
5	1		*658408772R FRONT BONNET INSULATOR (WCP)	Serviceable	330.62 F	*- F
6	1		*654704597R FRONT BONNET DAMPER LH (WCP)	Serviceable	125.66 F	*- F
7	1		*654704597R FRONT BONNET DAMPER RH (WCP)	Serviceable	125.66 F	*- F
8	1		*260101271R FRONT HEADLAMP RH (WCP)	Mtg Cracked	999.60 F	*892.50 F
9	1		*260602165R FRONT HEADLAMP LH (WCP)	Mtg Cracked	999.60 F	*892.50 F
10	1		*622907255R FRONT CENTRE BRACE BRACKET (WCP)	Repair	148.84 F	*- F
11	1		*620223972R FRONT BUMPER (WCP)	Cracked	1,877.34 F	*1,461.70 F
12	1		*625005785R FRONT SUPPORT PANEL (WCP)	Serviceable	1,360.00 F	*- F
13	4		*253A49995R FRONT PARKING SENSOR (WCP)	Serviceable	2,496.24 F	*- F
14	2		*2843896148R FRONT BLIND SPOT SENSOR RH (WCP)	Serviceable	810.20 F	*- F
15	1		*623821034R FRONT RADIATOR GRILLE BLACK (WCP)	Cracked	296.80 F	*296.80 F
16	1		*623855072R FRONT RADIATOR GRILLE MOULDING (CHROME) (WCP)	Cracked	261.80 F	*261.80 F
17	1		*622561964R FRONT RADIATOR GRILLE (WCP)	Cracked	530.60 F	*473.80 F
18	1		*628905855R FRONT GRILLE EMBLEM (WCP)	Cracked	187.04 F	*167.00 F
19	1		*620363937R FRONT RADIATOR TOP GARNISH (WCP)	Cracked	513.40 F	*513.40 F
20	1		*752106346R FRONT BUMPER REINFORCEMENT (WCP)	Repair	833.72 F	*- F
21	1		*620901789R FRONT BUMPER LOWER REINFORCEMENT GARNIS (WCP)	Serviceable	267.79 F	*- F
22	1		*7711428130 COOLANT 5L (WCP)	Not Necessary	27.10 F	*- F
23	1		*921004063R AIRCON CONDENSER (WCP)	Serviceable	1,041.60 F	*- F
24	1		*144614EA1B ENGINE INNER COOLER (WCP)	Serviceable	1,005.87 F	*- F
25	1		*214105169R RADIATOR (WCP)	Serviceable	812.44 F	*- F
26	1		*214819674R RADIATOR FAN COWLING ASSY (WCP)	Serviceable	1,049.66 F	*- F

Report was unsubmitted during this print-out.

9/14/22, 10:33 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*628109433R RADIATOR GRILLE INNER AIR DUCT (WCP)	Serviceable	185.13 F	*- F
28	1		*215595656R RADIATOR INNER AIR DUCT (WCP)	Serviceable	115.13 F	*- F
29	1		*215586371R INTERCOOLER AIR DUCT (WCP)	Serviceable	52.19 F	*- F
30	1		*214F62853R FRONT LOWER AIR INTAKE FLAP GUIDE (WCP)	Serviceable	669.08 F	*- F
31	1		*656220664 front bonnet lock handle (WCP)	Mtg Cracked	84.11 F	*84.11 F
Supplementary #1						
32	1	240704528R	*FRONT PARKING SENSOR HARDNESS (WCP)	Torn	238.03 F	*238.03 F
F=Franchise part.						
					Sub Total (\$\$)	19,464.15 7,138.78
					+ Margin on L,N Items 10.00/10.00% (\$\$)	1,946.41 713.88
					Total Parts (\$\$)	21,410.56 7,852.66
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	6	FRONT BUMPER SCREW (NECESSARY)	42.00	42.00
2	1	FRONT NUMBER PLATE (SERVICEABLE)	45.00	0.00
Sub Total (\$\$)			87.00	42.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE / WELADING REALIGN FROT BUMPER , BONNET, FRONT WINDS SUB FRAME, CHASSISD MEMBER FRONT ASSY LH/RH AND ALL NECESSARY ETC	New	1,200.00	500.00
2	TO REMOVE & REPLACE RADIATOR FAN , HOSE AND AIR COND CONDENSER HOSE , FAN INLUDING VECUUM AND TOP UP GAS	New	250.00	0.00
3	TO DIAGNOSTIC SETTING PASSENGER & DRIVER RESTRAINT SYSTEM AND RESETTNG OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00	0.00
4	TO RESPRAY FRONT ACCIDENT PORTION, BONNET,FENDER LH & RH, BUMPER CHASSIS MEMBERASSY RH/LH AND NECESSARY ETC	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,830.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >