

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22007309/KCM4**Date:** 05/09/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001990608

**Claimant Vehicle No :** SND8642H**Insured Vehicle No :** FBP4710A

Date of Loss: 29/07/2022

Nature of Claim: TP Claim No: 280720

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SND8642H**

Make &amp; Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4027471

Reg. Date: 01/04/2016 (Man. Year: 2015)

Chassis No: RU11107467

Colour: Metallic Pearl White

Odometer: 123785 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,728.00	2,326.80	401.20	14.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	970.00	130.00	11.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,828.00</b>	<b>3,296.80</b>	<b>531.20</b>	<b>13.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,828.00</b>	<b>2,600.00</b>	<b>1,228.00</b>	<b>32.08</b>

INSPECTION

Date of Assignment: 01/08/2022

Date Inspected: 03/08/2022 Inspected At:

Rc Auto-160 Sin Ming (HQ)  
160 SIN MING DRIVE, #06-20 SIN MING  
AUTOCITY  
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND8642H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,040.00 FL	*953.00 FL
2	1		*REAR BUMPER	Buckled	980.00 FL	*762.70 FL
3	1		*REAR BOOTLID GLASS MOULDING	Necessary	110.00 FL	*110.00 FL
4	1		*BOOTLID REFLECTOR	Cracked	450.00 FL	*413.20 FL
5	1		*REAR LAMP ASSY	Cracked	490.00 FL	*474.60 FL
6	1		*BUMPER SIDE (L/H)	Buckled/Dented	340.00 FL	*195.00 FL
					<b>Sub Total (S\$)</b>	<b>3,410.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>682.00</b>
					<b>Total Parts (S\$)</b>	<b>2,728.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REINSTATE WINDSCREEN	New	150.00	120.00
2	TO RESPRAY AFFECTED PORTION	New	500.00	450.00
3	LABOUR TO RENEW ABOVE PARTS	New	450.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,100.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >