

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007319/EQCE2**Date:** 16/12/2022**REFERENCE**

Insured/Claimant: DINESH KUMAR S/O TEVERMUTHU

Policy No: 2070165966-01

Date of Loss: 27/07/2022

Nature of Claim: OD

Claim No: 5891148264SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMW6617G**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: DEM027075

Reg. Date: 30/11/2020 (Man. Year: 2020)

Chassis No: WAUZZZF53MA011396

Colour: Blue

Odometer: 0 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$183,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18

Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	117,064.00	68,678.08	48,385.92	41.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	44,904.00	22,479.00	22,425.00	49.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	161,968.00	91,157.08	70,810.92	43.72
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	161,168.00	90,357.08	70,810.92	43.94
+ GST 7.00/7.00% (S\$)	11,281.76	6,325.00	4,956.76	43.94
Nett Amount (S\$)	172,449.76	96,682.08	75,767.68	43.94

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 01/08/2022 Inspected At: 24 Benoi Sector Singapore 629857
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 30.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,493.00 FS	*1,994.40 FS
2	2	*FRONT BUMPER SECURING STRIP	Necessary	79.00 FS	*63.20 FS
3	1	*FRONT BUMPER GRILLE - CENTER	Broken	219.00 FS	*174.80 FS
4	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	293.00 FS	*234.00 FS
5	1	*FRONT BUMPER SPOILER	Missing	599.00 FS	*478.80 FS
6	1	*FRONT BUMPER AIR GUIDE - LH / RH	N/S Missing	144.00 FS	*57.20 FS
7	1	*FRONT BUMPER CLOSING ELEMENT	Broken	293.00 FS	*234.00 FS
8	2	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Missing	302.00 FS	*240.80 FS
9	1	*FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH	N/S Missing	108.00 FS	*42.64 FS
10	1	*FRONT BUMPER TRIM - CENTER	Missing	127.00 FS	*101.60 FS
11	1	*RADIATOR GRILLE	Broken	1,881.00 FS	*1,504.80 FS
12	1	*RADIATOR COVER CAP	Not Necessary	141.00 FS	*- FS
13	1	*RADIATOR BRACKET	Not Necessary	19.00 FS	*- FS
14	1	*RADIATOR SECURING PLATE	Not Necessary	12.00 FS	*- FS
15	2	*FRONT PARKING AID SENSOR - INNER / OUTER	Missing	530.00 FS	*424.40 FS
16	1	*FRONT PARKING AID SENSOR ASSIST SYSTEM - SIDE	Missing	265.00 FS	*212.00 FS
17	4	*FRONT PARKING AID SEAL RING	Necessary	10.00 FS	*8.00 FS
18	1	*SET FRONT BUMPER WIRING	Torn	449.00 FS	*358.80 FS
19	1	*FRONT BUMPER FOAM FILLER PIECE	Broken	163.00 FS	*130.40 FS
20	1	*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
21	1	*FRONT BUMPER GUIDE SECTION - LH / RH	N/S Broken	82.00 FS	*32.24 FS
22	1	*FRONT BUMPER BRACKET - LH	Bent	254.00 FS	*203.20 FS
23	1	*FRONT BUMPER TOP COVER	Crushed	143.00 FS	*114.00 FS
24	1	*CAUTION SIGN	Necessary	16.00 FS	*12.40 FS
25	1	*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
26	1	*FRONT LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
27	2	*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
28	4	*POP RIVET	Necessary	4.00 FS	*2.88 FS
29	1	*FRONT HORN HIGH TONE - LH	Broken	134.00 FS	*106.80 FS
30	1	*FRONT HORN BRAKET - LH	Bent	33.00 FS	*25.68 FS
31	1	*FRONT FENDER - LH / RH	N/S Dented	2,378.00 FS	*951.20 FS
32	1	*FRONT FENDER ATTACHMENT PARTS	Necessary	55.00 FS	*44.00 FS
33	1	*FRONT FENDER CLOSING ELEMENT - LH	Necessary	83.00 FS	*65.84 FS
34	1	*FRONT FENDER BRACKET - LH	Bent	41.00 FS	*32.72 FS
35	1	*POP RIVET (11PCS)	Necessary	42.00 FS	*36.48 FS
36	1	*FRONT FENDER BRACKET - LH	Bent	65.00 FS	*51.44 FS
37	1	*FRONT FENDER BRACKET - RH	Bent	40.00 FS	*31.36 FS
38	1	*FRONT FENDER BRACE - LH	Bent	132.00 FS	*105.20 FS
39	1	*FRONT FENDER BRACKET - LH	Bent	55.00 FS	*44.00 FS
40	1	*FRONT FENDER COVER - LH	Broken	20.00 FS	*15.92 FS
41	1	*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	37.00 FS	*- FS
42	1	*FRONT FENDER WHEEL HOUSING LINER - LH	Torn	299.00 FS	*238.80 FS
43	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	176.00 FS	*140.80 FS
44	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	299.00 FS	*- FS
45	1	*FRONT WHEEL SPOILER - LH / RH	N/S Missing	164.00 FS	*65.12 FS
46	1	*FRONT SPOILER - LH	Missing	39.00 FS	*31.12 FS
47	1	*FRONT STONE CHIP GUARD - LH	Necessary	57.00 FS	*45.28 FS
48	1	*FRONT BRACKET TRIM - LH	Broken	27.00 FS	*20.96 FS
49	1	*FRONT FENDER TRIM - LH / RH	N/S Broken	342.00 FS	*136.40 FS
50	1	*BONNET	Dented	3,491.00 FS	*2,792.80 FS
51	1	*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	2	*FRONT LID HINGE - LH / RH	Bent	932.00 FS	*372.40 FS
53	3	*FRONT IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
54	1	*BONNET SOUND ABSORBER	Crushed	382.00 FS	*305.60 FS
55	1	*FRONT FENDER COVER - LH	Broken	81.00 FS	*64.24 FS
56	1	*FRONT FENDER COVER	Broken	40.00 FS	*31.44 FS
57	1	*FRONT HEADLAMPS COVER - LH	Broken	49.00 FS	*38.64 FS
58	1	*FRONT FENDER COVER - LH	Cut	18.00 FS	*13.92 FS
59	2	*BONNET ABSORBER	Not Necessary	256.00 FS	*- FS
60	1	*BONNET STRIKER - LH	Bent	56.00 FS	*44.56 FS
61	1	*BONNET LOCK	Bent	228.00 FS	*182.00 FS
62	1	*BONNET LOCK CABLE - RH	Not Necessary	82.00 FS	*- FS
63	1	*FRONT PLENUM CHAMBER COVER - RH	Cut	108.00 FS	*86.40 FS
64	1	*FRONT HEADLIGHT - LH	Broken	8,172.00 FS	*6,537.60 FS
65	1	*HOSE	Torn	42.00 FS	*32.88 FS
66	3	*FRONT COMPENSATING PIECE	Missing	136.00 FS	*108.00 FS
67	1	*FRONT LIFT CYLINDER BRACKET - LH	Missing	17.00 FS	*12.88 FS
68	1	*FRONT LIFT CYLINDER - LH	Missing	217.00 FS	*173.60 FS
69	1	*FRONT CORRUGATED PIPE	Torn	107.00 FS	*85.60 FS
70	1	*COOLANT RADIATOR LOCK CARRIER MOUNTING	Dented	1,127.00 FS	*901.60 FS
71	1	*FRONT COOLANT REGULATOR SUPPORT - LH	Broken	43.00 FS	*34.40 FS
72	1	*FLUID RESERVOIR AC CONDENSER (NPA)	Not Necessary	0.00 FS	*- FS
73	1	*A/C REFRIGERANT LINE (3PCS)	Bent (2Pcs Only)	844.00 FS	*370.40 FS
74	1	*A/C REFRIGERANT PIPE	Bent	585.00 FS	*468.00 FS
75	2	*FRONT A/C REFRIGERANT PIPE BRACKET	Broken	30.00 FS	*22.80 FS
76	1	*CHARGE AIR COOLER	Bent	654.00 FS	*522.80 FS
77	1	*PRESSURE PIPE	Not Necessary	496.00 FS	*- FS
78	1	*RADIATOR	Not Necessary	1,010.00 FS	*- FS
79	6	*FRONT READY-MIX COOLANT	Necessary	282.00 FS	*237.12 FS
80	1	*FRONT AIR GUIDE - LH / RH / UPPER / LOWER (4PCS)	N/S Broken(1pc only)	118.00 FS	*28.40 FS
81	1	*FRONT WINDSCREEN	Broken	1,625.00 FS	*1,300.00 FS
82	1	*FRONT RAIN SENSOR GEL FOIL	Necessary	130.00 FS	*104.40 FS
83	1	*FRONT RETAINING SPRING	Not Necessary	24.00 FS	*- FS
84	1	*FRONT CAMERA SILICONE PAD	Necessary	123.00 FS	*98.00 FS
85	1	*FRONT WINDSCREEN PRIMER	Necessary	22.00 FS	*17.36 FS
86	1	*FRONT WATER DEFLECTOR STRIP - LH / RH	N/S Cut	150.00 FS	*60.00 FS
87	1	*FRONT DOOR - LH	Dented	3,977.00 FS	*3,181.60 FS
88	1	*FRONT OUTER DOOR SEAL - LH	Necessary	247.00 FS	*197.20 FS
89	1	*BONDING AGENT	Necessary	51.00 FS	*40.56 FS
90	1	*CLEANING SOLUTION	Necessary	74.00 FS	*58.96 FS
91	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
92	1	*FRONT DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
93	1	*FRONT DOOR TRIM - LH / RH	N/S Broken	342.00 FS	*136.40 FS
94	1	*FRONT TRIM STRIP WINDOW SLOT SEAL - LH / RH	N/S Cut	892.00 FS	*356.80 FS
95	1	*ROOF MOULDING - LH / RH	N/S Torn	1,412.00 FS	*564.80 FS
96	1	*FRONT PILLAR A/B FRAME MEMBER - LH	Not Necessary	2,344.00 FS	*- FS
97	1	*FRONT SILL TRIM STRIP - LH	Not Necessary	133.00 FS	*- FS
98	1	*FRONT SIDE MEMBER TRIM - LH	Crushed	916.00 FS	*732.40 FS
99	1	*SECURING CLIPS ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
100	1	*ADHESIVE TAPES	Necessary	221.00 FS	*176.80 FS
101	1	*PICTOGRAM FOR AIRBAG / CHILDS SEAT STICKER	Not Necessary	27.00 FS	*- FS
102	1	*FRONT STEERING WHEEL AIRBAG	Broken	4,092.00 FS	*3,273.60 FS
103	1	*FRONT PASSENGER SIDE AIRBAG UNIT	Broken	4,853.00 FS	*3,882.40 FS
104	2	*FRONT HEAD AIRBAG UNIT - LH / RH	Broken	4,138.00 FS	*3,310.40 FS
105	1	*FRONT SPORTS STRNG WHEEL MULTIFUNCT	Cut	2,641.00 FS	*2,112.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
106	1		*FRONT DASHBOARD	Broken	5,901.00 FS	*4,720.80 FS
107	1		*FRONT WINDSCREEN DEFROSTER NOZZLE - RH	Broken	185.00 FS	*148.00 FS
108	1		*FRONT WINDSCREEN DEFROSTER NOZZLE - RH	Not Necessary	137.00 FS	*- FS
109	1		*FRONT MOULDED HEADLINER	Crushed	2,306.00 FS	*1,844.80 FS
110	2		*FRONT A-PILLAR TRIM - LH / RH	Broken	458.00 FS	*366.40 FS
111	2		*FRONT B-PILLAR TRIM - UPPER LH / RH	Not Necessary	520.00 FS	*- FS
112	2		*FRONT D-PILLAR TRIM - LH / RH	Broken	470.00 FS	*375.20 FS
113	2		*FRONT C-PILLAR TRIM - LH / RH	Not Necessary	332.00 FS	*- FS
114	4		*FRONT & REAR FOLDING GRAN HANDLE - LH / RH	Not Necessary	662.00 FS	*- FS
115	2		*FRONT THREE-POINT AUTOMATIC SEAT BELT - LH / RH	Jammed	2,454.00 FS	*1,963.20 FS
116	2		*FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH	Jammed	383.00 FS	*307.20 FS
117	1		*FRONT AIRBAG CONTROL UNIT	Necessary	2,364.00 FS	*1,891.20 FS
118	3		*FRONT AIRBAG CRASH SENSOR	Necessary	1,344.00 FS	*1,077.60 FS
119	1		*FRONT CENTRAL PROTECTION	Necessary	590.00 FS	*472.00 FS
120	1		*FRONT ALUMINIUM RIM (LH)	Broken	1,889.00 FS	*1,511.20 FS
121	1		*RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
122	1		*FRONT ASSEMBLY CARRIER	Bent	2,096.00 FS	*1,676.80 FS
123	1		*FRONT CONSOLE - LH	Bent	523.00 FS	*418.40 FS
124	1		*FRONT GEARBOX SUPPORT	Not Necessary	90.00 FS	*- FS
125	1		*FRONT GEARBOX MOUNTING	Not Necessary	235.00 FS	*- FS
126	1		*FRONT WISHBONE LINK - LH	Bent	605.00 FS	*483.60 FS
127	1		*FRONT SUSPENSION GUIDE - LH	Bent	1,057.00 FS	*845.60 FS
128	2		*FRONT & REAR UPPER GUIDE - LH	Bent	1,150.00 FS	*920.00 FS
129	1		*FRONT WHEEL BEARING HOUSING - LH	Bent	1,070.00 FS	*856.00 FS
130	1		*FRONT SWIVEL JOINT - LH	Necessary	214.00 FS	*170.80 FS
131	1		*FRONT WHEEL HUB - LH	Necessary	498.00 FS	*399.20 FS
132	1		*FRONT FLANGE DOUBLE ANGLED BALL BEARING - LH	Necessary	273.00 FS	*218.40 FS
133	1		*FRONT BEARING WHEELHUB - LH	Not Necessary	884.00 FS	*- FS
134	1		*FRONT SUSPENSION FORKS - LH	Bent	293.00 FS	*234.00 FS
135	2		*FRONT COUPLING ROD	Bent	258.00 FS	*103.20 FS
136	1		*FRONT ANTI-ROLL BAR MARKED GREEN	Bent	478.00 FS	*382.40 FS
137	1		*FRONT CONSTANT VELOCITY JOINTS DRIVE SHAFT	Not Necessary	2,999.00 FS	*- FS
138	1		*FRONT GAS SHOCK ABSORBER	Bent	342.00 FS	*273.60 FS
139	1		*FRONT STEERING RACK	Not Necessary	7,318.00 FS	*- FS
140	1		*FRONT TRACK ROD - LH	Not Necessary	109.00 FS	*- FS
141	1		*FRONT TIE ROD END - LH	Bent	217.00 FS	*173.60 FS
142	1		*FRONT LOWER NOISE INSULATION	Broken	640.00 FS	*512.00 FS
143	2		*FRONT CONNECTING PLATE - LH	Dented	520.00 FS	*415.20 FS
144	1		*FRONT FUSE HOLDER AND RELAY PLATE SIPPOT - LH	Broken	53.00 FS	*41.76 FS
145	1		*FRONT UNDERBODY TRIM - LH	Not Necessary	51.00 FS	*- FS
146	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
147	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
148	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
149	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
150	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
151	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
152	1		*LHS FRONT TYRE	Crushed	192.00 FS	*192.00 FS
153	1		*SUNDRIES	Necessary	1,000.00 FS	*376.96 FS
154	1		*SHOCK ABSORBER MOUNTING - LH UPPER (Supplementary)	Bent	104.00 FS	*82.80 FS
155	1		*SPRING SUPPORT - LH (Supplementary)	Necessary	69.00 FS	*54.80 FS
156	1		*ABS UNIT WITH CONTROL UNIT (Supplementary)	Not Necessary	7,696.00 FS	*- FS
157	1		*BRACKET (Supplementary)	Broken	57.00 FS	*45.52 FS
158	1		*BRACKET PIPE - LH (Supplementary)	Bent	63.00 FS	*49.84 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
159	1	*BRACKET PIPE - RH (Supplementary)	Bent	63.00 FS	*49.84 FS
160	1	*BRACKET PIPE - LH (Supplementary)	Bent	61.00 FS	*48.16 FS
161	1	*BRACKET FLUID (Supplementary)	Necessary	35.00 FS	*27.68 FS
162	1	*BATTERY (Supplementary)	Not Necessary	644.00 FS	*- FS
163	1	*RETAINING FRAME - LH (Supplementary)	Broken	51.00 FS	*40.40 FS
164	1	*RADIATOR SUPPORT (Supplementary)	Not Necessary	85.00 FS	*- FS
165	1	*NOISE INSULATION PLATE (Supplementary)	Missing	28.00 FS	*22.32 FS
166	1	*LEVEL SENSOR - LH (Supplementary)	Broken	363.00 FS	*290.00 FS
167	1	*SPEED SENSOR - FRONT (Supplementary)	Broken	129.00 FS	*103.20 FS
168	1	*BRAKE DISC (Supplementary)	Cut	266.00 FS	*212.80 FS
169	1	*BRAKE DISC COVER PLATE - LH (Supplementary)	Bent	98.00 FS	*77.68 FS
170	1	*BRAKE HOSE (Supplementary)	Bent	86.00 FS	*68.16 FS
171	2	*BRAKE LINE BRACKET (Supplementary)	Bent	10.00 FS	*6.56 FS
172	1	*RETAINER FOR BRAKE HOSE (Supplementary)	Bent	30.00 FS	*23.68 FS
173	2	*HOSE BRACKET (Supplementary)	Necessary	5.00 FS	*4.08 FS
174	1	*RETAINER FOR CONTROL UNIT (Supplementary)	Broken	64.00 FS	*51.20 FS
175	1	*WIRE CONNECTION - 2PIN (Supplementary)	Broken	23.00 FS	*18.40 FS
176	1	*WIRE CONNECTION - 8PIN (Supplementary)	Broken	24.00 FS	*18.96 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 117,064.00 68,678.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	0.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
5	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
6	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
8	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
9	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
10	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
11	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
12	TO PLACE VEHICLE ON CAR O-LINER	New	2,400.00	0.00
13	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
14	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR	New	280.00	280.00
15	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
16	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE	New	280.00	280.00
17	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS LHS SILL PANEL TRIM AND LHS FRONT DOOR. TO REPAIR RHS FRONT DOOR AND BOTH UPPER A-PILLARS. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR WITH LHS SILL PANEL. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	14,400.00	5,000.00
18	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS, BOTH UPPER A-PILLARS, LHS A-PILLAR, LHS SILL PANEL, DOOR ENTRANCE, LHS SILL PANEL TRIMS AND LHS FRONT FENDER TOP SUPPORT	New	11,000.00	3,575.00
19	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
20	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK	New	384.00	384.00
21	TO REMOVE AND RENEW ABS UNIT WITH DAMAGES BRAKE PIPE. TO CARRY OUT BRAKE BLEEDING	New	1,600.00	1,600.00
Gross Labour Cost (\$\$)			44,904.00	22,479.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >