

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS4/ICS22007322/TVY3E2

Date: 22/08/2022

REFERENCE

Insured/Claimant: SONG JUN YANG, SIMON Policy No: MPC21P0019500
Date of Loss: 31/07/2022 Nature of Claim: OD Claim No: DMPC2200326H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD9920K**
Make & Model: MERCEDES-BENZ C200, 2.0 AMG (A) Engine No: 27492030612914
Reg. Date: 03/05/2017 (Man. Year: 2016) Chassis No: WDD2050422R171783
Colour: White Odometer: 0 km
Engine Capacity: 1991 cc
Market Value/New Car Price: S\$126,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	-500.00	-500.00	0.00	0.00

INSPECTION

Date of Assignment: 01/08/2022 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)
Yew Tee Automobile Tech Pte Ltd (HQ)
Date Inspected: 02/08/2022 Inspected At: Blk 25 Kaki Bukit Road 4
#01-61 Synergy @ Kaki Bukit
Singapore 417800
Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$126,000.00
OMV :	\$41,382.00
PARF Rebate (1) :	\$31,454.00
Quota Premium Paid :	\$48,556.00
COE Rebate (2) :	\$22,899.00
Total Rebate (1) + (2) = :	\$54,353.00

The total amount incurred will be Market Value \$126,000.00 minus Total Rebate \$54,353.00 = \$71,647.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2022)
Parts:	192	MERCEDES-BENZ C200 2.0 AMG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD9920K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air cleaner		-	-
2	1		Air cleaner air flow duct		-	-
3	1		Air cleaner air flow sensor		-	-
4	1		Air cleaner cover		-	-
5	1		Air cleaner element		-	-
6	1		Air cleaner heater duct		-	-
7	1		Air cleaner hose		-	-
8	1		Air cleaner housing		-	-
9	1		Air-cond compressor		-	-
10	1		Air-cond compressor V belt		-	-
11	1		Air-cond condenser		-	-
12	1		Air-cond discharge hose		-	-
13	1		Air-cond fan blade		-	-
14	1		Air-cond fan motor		-	-
15	1		Battery bracket		-	-
16	1		Battery cable		-	-
17	1		Battery cable [+]		-	-
18	1		Battery cable [-]		-	-
19	1		Battery clamp		-	-
20	1		Battery earth cable		-	-
21	1		Battery panel		-	-
22	1		Battery tray		-	-
23	1		Bonnet		-	-
24	1		Bonnet adjustable stopper LH		-	-
25	1		Bonnet adjustable stopper RH		-	-
26	1		Bonnet cable		-	-
27	1		Bonnet hinge LH		-	-
28	1		Bonnet hinge RH		-	-
29	1		Bonnet insulator		-	-
30	1		Bonnet insulator clips		-	-
31	1		Bonnet lock		-	-
32	1		Bonnet rubber		-	-
33	1		Bonnet rubber clip		-	-
34	1		Bonnet rubber inner		-	-
35	1		Bonnet rubber inner clip		-	-
36	1		Bonnet rubber LH		-	-
37	1		Bumper air grille center, front		-	-
38	1		Bumper clip, front		-	-
39	1		Fender LH, front		-	-
40	1		Fender moulding LH, front		-	-
41	1		Fender shield clip LH, front		-	-
42	1		Fender shield LH, front		-	-
43	1		Fuse box		-	-
44	1		Fuse box cover		-	-
45	1		Headlamp bulb LH		-	-
46	1		Headlamp LH		-	-

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		Radiator		-	-
48	1		Radiator fan blade		-	-
49	1		Radiator fan motor		-	-
50	1		Radiator grille		-	-
51	1		Radiator lower hose		-	-
52	1		Radiator mounting lower		-	-
53	1		Radiator mounting upper		-	-
54	1		Radiator panel		-	-
55	1		Radiator upper hose		-	-
56	1		Relay, air-cond		-	-
57	1		Relay, battery		-	-
58	1		Relay, box main body		-	-
59	1		Relay, headlamp		-	-
60	1		W/screen glass, front		-	-
61	1		Wheelhouse LH, front		-	-
62	1		Wiper air grille		-	-
63	1		Wiper air grille clips		-	-
64	1		Wiper arm cover LH, front		-	-
65	1		Wiper arm cover RH, front		-	-
66	1		Wiper arm LH, front		-	-
67	1		Wiper arm RH, front		-	-
68	1		Wiper blade LH, front		-	-
69	1		Wiper blade RH, front		-	-
70	1		Wiper blade rubber LH, front		-	-
71	1		Wiper blade rubber RH, front		-	-
72	1		Wiper link, front		-	-
73	1		Wiper motor, front		-	-
74	1		Wiper nozzle LH, front		-	-
75	1		Wiper panel		-	-
76	1		Wiper tank motor, front		-	-
77	1		Wiper tank, front		-	-
78	1		Wiper tube Y joint		-	-
79	1		Alternator		-	-
80	1		Alternator & water pump V belt		-	-
81	1		Engine		-	-
82	1		Engine cylinder head		-	-
83	1		Engine cylinder head gasket		-	-
84	1		Engine electronic control relay		-	-
85	1		Engine electronic control unit		-	-
86	1		Engine mounting LH		-	-
87	1		Engine mounting RH		-	-
88	1		Engine oil filter		-	-
89	1		Engine oil filter casing		-	-
90	1		Engine oil filter casing gasket		-	-
91	1		Engine oil intercooler pipe		-	-
92	1		Engine oil pressure switch		-	-
93	1		Engine rocker cover		-	-
94	1		Engine water pump		-	-
95	1		Intercooler, turbo charger		-	-
96	1		Spark plug cable no. 1		-	-
97	1		Spark plug cable no. 2		-	-
98	1		Spark plug cable no. 3		-	-
99	1		Spark plug cable no. 4		-	-
100	1		Absorber bush LH, front		-	-
101	1		Absorber LH, front		-	-
102	1		Air-cond blower		-	-
103	1		Air-cond cooling coil		-	-
104	1		Dashboard		-	-

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	Repair	-	-
2	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	Repair	-	-
Labour Items				
3	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair	Repair	-	-
4	To Carry-Out Body Cavity Preservation.	Repair	-	-
5	To Online ECU Programming.	Repair	-	-
6	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	Repair	-	-
7	To Do Up Interior Cleaning and Chemical Wash.	Repair	-	-
8	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	Repair	-	-
9	To Dismantle and Refit Engine, Gearbox.	Repair	-	-
10	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	Repair	-	-
11	To Dismantle and Refit Front Windscreen Glass.	Repair	-	-
12	Towing Charges.	Repair	-	-
13	To Dismantle and Refit Front Undercarriage.	Repair	-	-
14	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	Repair	-	-
15	To Conduct Computer Wheel Alignment.	Repair	-	-
Gross Labour Cost (S\$)			0.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >