

ASS. REC. BY: Taugh

REF:

INC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / CP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Lim TS Vehicle: IN / OUT

Veh No: SHC 8200B Yr Regn: 2016, June
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /
Truck / Trailer or _____
Make: Hyundai 140 C.C. 1685
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 546765 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KMHLCB414MG 4091330
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NI / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: 205/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Wootche
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 27/6/22
Survey held at Comfort Lodge
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FR + N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP-INC-PA6024Y

Date/Time, File Pass to? ☐ : Prell. Report
Date/Time, File Return to? ☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

1) _____
2) _____
Rep. Format: _____
Lump Sum / I.B.L. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____	
Transportation: _____	
Photos _____	
Others _____	
TOTAL _____	

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 27.06.2022MODEL: Hyundai i40VEHICLE NO.: SHC8200BINSURANCE: NTUCMVA: LIM T S

(SAS-KIV)

LKK -

CLISJ

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Side Bracket LH	1		\$ 22.40
	Front Fender LH	1		\$ 663.00
	Front Fender Shield LH	1		\$ 174.90
	Front Fender Retainer LH	1		\$ 217.20
	HeadLamp LH	1		\$ 1,388.00
	Front Wheel Cap LH	1		\$ 217.20
	Headlamp Support Panel	1		\$ 907.40
	Wing Mirror LH	1		\$ 670.00
	SUB TOTAL			\$ 5,334.30
	LESS 20%			\$ 1,066.86
	DISCOUNTED TOTAL			\$ 4,267.44
	Frt Wheel Tyre LH	1		\$ 216.00
	Labour Charge			
	Panel Beating - <u>Rear Fender LH etc</u>			\$ 1,200.00
	Spray Painting Charge - <u>Rear Fender LH etc</u>			\$ 1,200.00
	Check Lightings			\$ 40.00
	Tuff Kote			\$ 40.00
	Wheel Alignment			\$ 120.00
	Towing Fee			-
	TOTAL LABOUR			\$ 2,600.00
	ESTIMATE TOTAL			\$ 7,083.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 92495749
 WP, 28/12/22 e 450
 C/B rising after repair
 Tanpin C. Khantawon
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S

E

Date/Time: 27.06.2022 15:39

Page : 1

um: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299712

JC NO305521308

MEMER

COMFORT TRANSPORTATION PTE LTD

MEMER NO. 7010045

SS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

UNT CARD NO.

REGN NO.:

SHC8200B

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

26.06.2022 20:45

YR OF MANU.

09.06.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU091330

COMPLETION DATE/TIME:

cident Date: 26.06.2022

TURE: 3P 26.06.2022

JOB DESCRIPTION

NO

0010

0020

LABOR CODE


PB

23-01

DESCRIPTION

LUMP SUM REPAIR-SHC8200B-TP

TOWING FEE



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.:

SHC8200B

LIMITS

Vehicle No.:

SHC8200B

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard