

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AUTOMOBILE INSI	LOTT	ON KEI OKI		
INCOME INSURANCE LTD Ref: NS/INC22007331/Tvcm4						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	29-09-2022 INC4		
1.						
••	Insured Veh. SLA 8808L Veh. Inspected SH 9839X				SH 9839X	
	Policy No.	01,100001		age (\$)	0.00	
	Claim No.	MT/1182252-002	Exces		0.00	
	Assign From		Assign		01/08/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVKU164717	Colou		BLUE	
	Odometer	226095	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/07/2022		tion Date	01/08/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				