



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4478Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	553.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	228.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
10	REAR BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
2	REAR BUMPER BRACKET LH/RH @\$35.60	NOT NECESSARY	71.20	-
2	REAR BUMPER REFLECTOR LH/RH @\$32.00	NOT NECESSARY	64.00	-
	LESS 20% DISCOUNT		-273.32	-
			1,093.28	-
	<b><u>NETT ITEMS</u></b>			
1	REAR BUMPER MAT (N)	NOT NECESSARY	50.00	-
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	135.70	-
	LESS 10% DISCOUNT		-18.57	-
			167.13	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER.		450.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
	CHECK LIGHTING & WIRING.	NOT NECESSARY	40.00	-
			850.00	560.00
<b>GRAND TOTAL</b>			<b>2,110.41</b>	<b>560.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>560.00</b>

Report Ref No. NS/INC22007333/Tvcm4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.