

ASS. REC. BY: Taught

REF:

INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

AlwaysVeh No: SHS4478ZYr Regn: 2012 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: HyundaiC.C. 1685

Colour \_\_\_\_\_

A/C: Insured / Std / NI / NA

Sp. Reading 561174

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCB414M14 4/00007

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wetake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 1/8/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) \_\_\_\_\_  
Date/Time, File Return to?☐ : Final Report

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (?) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Date/Time: 01.08.2022 12:50

Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4493537

JC NO: 305525031

ISTOMER

3/MS COMFORT TRANSPORTATION PTE LTD  
7010045

ISTOMER NO. 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

ADDRESS 65508755  
L. (R) (P) (O)


3COUNT CARD NO.

REGN NO: <b>SHB4478Z</b>	MILEAGE
MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL <b>I-40</b>	DATE/TIME IN <b>01.08.2022 10:25</b>
YR OF MANU. <b>20.12.2017</b>	TARGET DATE
CHASSIS CODE <b>KMHLB41UMHU100007</b>	COMPLETION DATE/TIME:

ccident Date: 30.07.2022  
ATURE: 3P 30.07.2022

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

Vehicle No.: **SHB4478Z**  
CHIANG

Vehicle No.: **SHB4478Z**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard



# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHB4478Z

30.07.2022

MAKE REG: 20.12.2017

MODEL HYU- I40

Type

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Rx \$553.00
1	REAR BUMPER LOWER COVER			X \$228.00
1	REAR BUMPER REINFORCEMENT			X \$428.40
10	REAR BUMPER CLIPS		\$2.20	Rx \$22.00
2	REAR BUMPER BRACKET LH/RH		\$35.60	X \$71.20
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	X \$64.00
	<b>SUB TOTAL</b>			<b>\$1,366.60</b>
	<b>20.00%</b>			<b>\$273.32</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,093.28</b>
1	REAR BUMPER MAT			X \$50.00
1	REAR REVERSE SENSOR			? \$135.70
				<b>\$167.13</b>
	<b>Labour Charge</b>			
	Panel Beating		280	\$450.00
	Spray Painting Charge		250	\$300.00
	Remove/refix reverse sensor		30	\$60.00
	Check Lighting & Wiring		X	\$40.00
	<b>TOTAL LABOUR</b>			<b>\$850.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,943.28</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphie 97495749  
WP 1/8/770 5 pm  
2 days  
1/5/2022 at the repair  
Tanphie elluhandan