

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6213H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT FENDER LH	TO REPAIR SEE LABOUR	1,111.93	-
1	FRT FENDER EMBLEM LH	NOT NECESSARY	86.50	-
1	REAR DOOR ASSY LH	TO REPAIR SEE LABOUR	1,258.30	-
1	FRT DOOR ASSY LH	TO REPAIR SEE LABOUR	1,264.00	-
1	REAR BUMPER ASSY	TO REPAIR SEE LABOUR	503.04	-
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	94.80	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-1,085.14	-
			3,255.43	-
	NETT ITEMS			
1	FRT DOOR COMFORT LOGO (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LOGO (N)	NECESSARY	80.00	80.00
1	PATROL STICKER (N)	NECESSARY	30.00	30.00
1	BUMPER MAT (N)	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-	-18.50
			235.00	166.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER LH, REAR DOOR ASSY LH, FRT DOOR ASSY LH, & REAR BUMPER ASSY.		1,400.00	525.00
	SPRAY PAINT.		1,200.00	750.00
	REMOVE / REFIX DOOR PARTS.	NOT NECESSARY	240.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	ADVERTISEMENT LOGO.	CUT	450.00	300.00
			3,340.00	1,575.00
	GRAND TOTAL		6,830.43	1,741.50

Report Ref No. NS/INC22007334/Tcm4





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,400.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC22007334/Tcm4

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**