

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007338/KQY3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00011442200

Claimant Vehicle No : GZ8855C **Insured Vehicle No :** SFV6880A

Date of Loss: 24/07/2022 Nature of Claim: TP Claim No: SNM22D205149/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ8855C**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2723868

Reg. Date: 18/08/2017 (Man. Year: 2017) Chassis No: JTFAT35Y90K208403

Colour: White Odometer: 153741 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: JK TYRE 7 mm Rear Left Side: Condor 9/9 mm

Front Right Side: JK TYRE 7 mm Rear Right Side: Condor 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,283.00	1,233.00	1,050.00	45.99
Miscellaneous Items	419.00	419.00	0.00	0.00
Labour	2,970.00	2,510.00	460.00	15.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,672.00	4,162.00	1,510.00	26.62
Approved Total (Overridden) (\$\$)		3,300.00		
(\$\$)	5,672.00	3,300.00	2,372.00	41.82
+ GST 7.00/7.00% (\$\$)	397.04	231.00	166.04	41.82
Nett Amount (\$\$)	6,069.04	3,531.00	2,538.04	41.82

INSPECTION

Date of Assignment: 11/08/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 10/08/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Sep 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ8855C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Buckled / Cracked	240.00 F	*240.00 F
2	1		*1 PC FRT PANEL	Bent	420.00 F	*420.00 F
3	1		*1 PC FRT PANEL EMBLEM (DYNA)	Necessary	35.00 F	*35.00 F
4	1		*1 PC TAILGATE	Bent	520.00 F	*520.00 F
5	1		*1 PC TAILGATE STICKER (DYNA)	Necessary	18.00 F	*18.00 F
6	1		*1PC AIR-CON EVAPORATOR	Serviceable	1,050.00 F	*- F

F=Franchise part.

Total Parts (S\$)	2,283.00	1,233.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NUMBER PLATE (BENT)	25.00	25.00
2	1	1 PC REAR STEP TRAY (DISTORTED)	150.00	150.00
3	1	1 PC STICKER - 13 PAX (NECESSARY)	10.00	10.00
4	1	1 PC STICKER - 70KM/H (NECESSARY)	10.00	10.00
5	1	1 SET REVERSE SENSOR (DENTED)	200.00	200.00
6	1	12 PCS TAILGATE RIVETS @2/PC (NECESSARY)	24.00	24.00
Sub Total (\$\$)			419.00	419.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX TAILGATE,REAR STEP TRAY,TRANSFER TAILGATE INNER PROTECTOR,KNOCK & REPAIR REAR LH CORNAL PILLAR AND REALIGN THE SAME	New	450.00	400.00
2	PUTTY & RESPRAY ON TAILGATE,STEP TRAY,REAR LOWER MEMBER	New	450.00	400.00
3	REMOVE & REFIX FRT WINDSCREEN GLASS	New	60.00	60.00
4	REMOVE & REFIX DASHBOARD,METER AND CHECK WIRING	New	280.00	250.00
5	REMOVE & REFIX AIR-CON,CHECK,VACUUM & REFILL GAS	New	100.00	100.00
6	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,CHECK HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL AND REALIGN THE SAME	New	680.00	600.00
7	PUTTY & RESPRAY ON FRT PANEL,GRILLE,FRT BUMPER	New	600.00	500.00
8	TO REWRITE ADVERTISEMENT	New	350.00	200.00
Gross Labour Cost (\$\$)			2,970.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >