

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22007339/AVY3Q2**Date:** 29/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBE2089G **Insured Vehicle No :** YP9197B
 Date of Loss: 29/07/2022 Nature of Claim: TP Claim No: DMCG22001536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE2089G**
 Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KC400D054699
 Reg. Date: 22/09/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0107049
 Colour: White Odometer: 211011 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175 R14C Rear Tyre Size: 175 R14C
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,991.51	5,105.36	4,886.15	48.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,510.00	3,190.00	67.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,691.51	6,615.36	8,076.15	54.97
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	14,691.51	5,200.00	9,491.51	64.61
+ GST 7.00/7.00% (S\$)	1,028.41	364.00	664.41	64.61
Nett Amount (S\$)	15,719.92	5,564.00	10,155.92	64.61

INSPECTION

Date of Assignment: 02/08/2022
 Date Inspected: 10/08/2022 Inspected At: Sm Automotive - Kaki Bukit (HQ)
 BLOCK C - 1, KAKI BUKIT AVE 6, #01-43
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Sep 2022)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE2089G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE LH	Dented	1,548.40 FL	*1,285.00 FL
2	2		*REAR TAILGATE HINGE LH	Not Necessary	205.80 FL	*- FL
3	1		*REAR TAILGATE CHECKER LH	Not Necessary	98.20 FL	*- FL
4	1		*REAR TAILGATE EMBLEM LOGO LH	Necessary	155.10 FL	*155.10 FL
5	1		*REAR TAILGATE EMBLEM NV200 LH	Necessary	175.38 FL	*175.38 FL
6	1		*REAR TAILGATE OUTER MOULDING LH	Cracked	336.10 FL	*336.10 FL
7	1		*REAR TAILGATE OUTER HANDLE LH	Not Necessary	149.80 FL	*- FL
8	1		*REAR TAILGATE TOP LOCK LH	Not Necessary	262.00 FL	*- FL
9	1		*REAR TAILGATE LOWER LOCK LH	Damaged	190.60 FL	*190.60 FL
10	1		*REAR TAILGATE WEATHERSTRIPE LH	Not Necessary	196.40 FL	*- FL
11	1		*REAR TAILGATE RH	Dented	1,542.30 FL	*1,300.00 FL
12	2		*REAR TAILGATE HINGE RH	Not Necessary	205.80 FL	*- FL
13	1		*REAR TAILGATE CHECKER RH	Not Necessary	98.20 FL	*- FL
14	1		*REAR TAILGATE EMBLEM DCI RH	Necessary	66.20 FL	*66.20 FL
15	1		*REAR TAILGATE TOP LOCK RH	Not Necessary	262.00 FL	*- FL
16	1		*REAR TAILGATE LOWER LOCK RH	Damaged	190.60 FL	*190.60 FL
17	1		*REAR TAILGATE WEATHERSTRIPE RH	Not Necessary	196.40 FL	*- FL
18	2		*REAR TAILLAMP	Not Necessary	970.20 FL	*- FL
19	1		*REAR BUMPER	Deformed	789.40 FL	*789.40 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 FL	*70.40 FL
21	1		*REAR BUMPER REFLECTOR	N/S Cracked	73.00 FL	*36.50 FL
22	1		*REAR BUMPER SPONGE	Cracked	154.80 FL	*154.80 FL
23	1		*REAR END PANEL OUTER	Repair	386.20 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Cracked	178.10 FL	*178.10 FL
25	1		*REAR WEATHER STRIPE	Not Necessary	290.30 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	4		*REAR TAILLAMP CLIPS	Not Necessary	24.00 FS	*- FS
28	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
29	1		*REAR TAILGATE 70KM/H STICKER LH	Necessary	25.00 FS	*10.00 FS
30	1		*LH REAR TAILGATE COMPANT STICKER	Necessary	120.00 FS	*80.00 FS
31	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
32	1		*REAR REVERSE CAMERA	Damaged	350.00 FS	*300.00 FS
33	1		*REAR FLOOR PANEL TOP RUBBER MAT	Not Necessary	800.00 FS	*- FS
34	2		*BOTH REAR WINDSCREEN GLASS SEALANT	Necessary	160.00 FS	*40.00 FS
35	1		*REAR TAILLAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,870.68	5,598.18
- List Item Discount on L Items 10.00/10.00% (\$\$)	879.17	492.82
Total Parts (\$\$)	9,991.51	5,105.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,600.00	600.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	60.00
5	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	300.00	60.00
6	LABOUR FOR REMOVE & RENEW BOTH REAR WINDSCREEN GLASS	New	300.00	60.00
7	TO CONDUCT WATER CHECK LEAKAGE	New	120.00	0.00
8	LABOUR FOR REMOVE & RENEW REAR REVERSE SENSOR /CAMERA	New	200.00	100.00
			Gross Labour Cost (\$\$)	4,700.00
				1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >