

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22007344/KQY3E2

Date: 29/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW000216792100
Claimant Vehicle No: SKW3485M Insured Vehicle No: CHINATAIPING
Date of Loss: 27/07/2021 Nature of Claim: TP Claim No: SNM22D205247/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW3485M**
Make & Model: VOLKSWAGEN PASSAT CC, 1.8 TSI (A) Engine No: CJS122195
Reg. Date: 27/10/2015 (Man. Year: 2015) Chassis No: WVVZZZ3CZGE059735
Colour: Metallic Grey Odometer: 64656 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,945.00	200.00	3,745.00	94.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	789.60	168.00	621.60	78.72
Paintwork Labour	180.60	117.60	63.00	34.88
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,915.20	485.60	4,429.60	90.12
+ GST 7.00/7.00% (S\$)	344.06	33.99	310.07	90.12
Nett Amount (S\$)	5,259.26	519.59	4,739.67	90.12

INSPECTION

Date of Assignment: 10/08/2022

Date Inspected: 15/08/2022 Inspected At:

BLK 10 #01-20 SIN MING IND EST SEC S
SINGAPORE 575645
Repairer:Ding Auto Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2022)
Parts:	143	VOLKSWAGEN PASSAT CC 1.8 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW3485M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*R/OUTER SILL COVER (NPA)	Serviceable	0.00 F	*- F
2	1	NA	*R/R BUMPER GUIDE	Serviceable	45.00 F	*- F
3	1	NA	*R/RR SHOCK ABSORBER	Serviceable	260.00 F	*- F
4	1	NA	*R/RR WHEEL (LOCAL REPAIR)	Dented	1,400.00 F	*200.00 FS
5	1	NA	*R/R WHEELHOUSE CVR	Serviceable	160.00 F	*- F
6	1	NA	*R/R WHEEL HUB/BRG	Not Necessary	380.00 F	*- F
7	1	NA	*R/SIDE PANEL	Repair	1,400.00 F	*- F
8	1	NA	*REAR DOOR CHROME	Serviceable	300.00 F	*- F
9	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*- F
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,945.00	200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	180.60	117.60
<u>Labour Items</u>				
2	Total Panel/Mechanical Labour	New	789.60	168.00
Gross Labour Cost (\$)			970.20	285.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >