

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22007346/UVY3E2

Date: 15/08/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : GBE19Y **Insured Vehicle No :** SJA1467G
Date of Loss: 28/07/2022 Nature of Claim: TP Claim No: DMPC2200323H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE19Y**
Make & Model: TOYOTA REGIUS ACE, 3.0 D DX (A) Engine No: 1KD2537298
Reg. Date: 13/08/2015 (Man. Year: 2015) Chassis No: KDH2010171542
Colour: White Odometer: 85894 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,423.40	7,499.87	7,923.53	51.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,010.00	1,890.00	48.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,323.40	9,509.87	9,813.53	50.79
Approved Total (Overridden) (S\$)		7,600.00		
(S\$)	19,323.40	7,600.00	11,723.40	60.67
+ GST 7.00/7.00% (S\$)	1,352.64	532.00	820.64	60.67
Nett Amount (S\$)	20,676.04	8,132.00	12,544.04	60.67

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 02/08/2022 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Aug 2022)	
Parts:	N/A	TOYOTA REGIUS ACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE19Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,499.80 F	*- FL
2	1		*TAILGATE	Dented	2,159.10 F	*2,159.10 FL
3	1		*TAILGATE OUTER HANDLE	Cracked	455.80 F	*399.80 FL
4	1		*TAILGATE INNER LOCK	Dented / Shorted	425.80 F	*425.80 FL
5	1		*TAILGATE INNER LOCK ACTUATOR	Damaged	455.20 F	*455.20 FL
6	1		*TAILGATE LOCK STRIKER	Not Necessary	45.00 F	*- FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	399.80 F	*399.80 FL
8	2		*TAILGATE DAMPERS	Not Necessary	732.20 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	455.10 F	*455.10 FL
10	1		*TAILGATE REAR LOGO	Necessary	85.00 F	*85.00 FL
11	1		*REAR BUMPER SPORT (FIBER JAPAN)	Cracked	1,800.00 F	*1,650.00 FL
12	1		*REAR BUMPER STEP BRACKET	Bent	166.80 F	*166.80 FL
13	4		*REAR BUMPER LOWER BRACKETS	Bent	140.00 F	*140.00 FL
14	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	210.00 F	*- FL
15	1		*REAR END PANEL OUTER	Dented	981.10 F	*885.10 FL
16	1		*REAR END PANEL INNER	Repair	988.50 F	*- FL
17	1		*REAR END PANEL TOP PLATE	Twisted	366.80 F	*281.10 FL
18	2		*TAILLAMPS	Cracked	1,300.00 F	*1,030.20 FL
19	1		*TAILLAMP LOWER GARNISHS	N/S Dented	330.00 F	*165.00 FL
20	1		*TAILLAMP HOUSING PANELS	N/S Bent	977.00 F	*488.50 FL
21	1		*REAR SPARE TYRE BRACKET	Not Necessary	455.10 F	*- FL
22	1		*REAR SPARE TYRE BRACKET HOLDER	Not Necessary	165.30 F	*- FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
24	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
25	1		*REAR 70 KM/H STICKER	Necessary	50.00 FS	*10.00 FS
26	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
27	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*40.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
31	1		*REAR EXHAUST HEAT SHIELD O/S	Bent	200.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,423.40	9,796.50
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	2,296.63
Total Parts (\$)	15,423.40	7,499.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$)			3,900.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >