

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007347/KVY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00149402101		
Claimant Vehicle No :	SKX9201X	Insured Vehicle No :	GBF6038Y		
Date of Loss:	30/07/2022	Nature of Claim:	TP	Claim No:	SNM22D205327/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX9201X		Engine No:	P520337297
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)		Chassis No:	JM6BM42A8G0328491
Reg. Date:	31/12/2015 (Man. Year: 2015)		Odometer:	113885 km
Colour:	Metallic Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	FRONWAY 9 mm	Rear Left Side:	FRONWAY 9 mm
Front Right Side:	FRONWAY 9 mm	Rear Right Side:	FRONWAY 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,295.20	2,922.16	3,373.04	53.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,960.00	890.00	31.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,145.20	4,882.16	4,263.04	46.62
Approved Total (Overridden) (\$\$)		3,900.00		
Nett Amount (\$\$)	9,145.20	3,900.00	5,245.20	57.35

INSPECTION

Date of Assignment:	02/08/2022	
Date Inspected:	03/08/2022 Inspected At:	Kent Seng Car Services (HQ) BLK 1017 YISHUN INDUSTRIAL PARK A #01-240 Singapore 768759
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX9201X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT SIDE FENDER	Bent	406.00 F	*350.60 FL
2	1		*FRONT RIGHT SIDE FENDER INNER COWLING	Distorted	219.20 F	*175.10 FL
3	8		*FRONT LEFT SIDE FENDER INNER COWLING CLIPS	Necessary	32.00 F	*32.00 FL
4	1		*FRONT RIGHT SIDE DOOR	Bent	1,201.00 F	*1,021.00 FL
5	1		*FRONT RIGHT SIDE DOOR INNER BOARD	Serviceable	1,012.00 F	*- FL
6	10		*FRONT RIGHT SIDE DOOR INNER BOARD CLIPS	Not Necessary	50.00 F	*- FL
7	1		*FRONT RIGHT SIDE DOOR CHROME PROTECTOR (UPPER)	Serviceable	81.00 F	*- FL
8	1		*FRONT RIGHT SIDE DOOR RUBBER	Serviceable	112.00 F	*- FL
9	1		*FRONT RIGHT SIDE DOOR VERTICAL BLACK STICKER	Necessary	68.00 F	*68.00 FL
10	1		*FRONT RIGHT SIDE DOOR HORIZONTAL BLACK STICKER	Necessary	81.00 F	*81.00 FL
11	1		*FRONT RIGHT SIDE DOOR GEAR	Serviceable	126.00 F	*- FL
12	1		*FRONT RIGHT SIDE DOOR GEAR MOTOR	Serviceable	149.00 F	*- FL
13	1		*FRONT RIGHT SIDE DOOR CHANNEL	Serviceable	174.00 F	*- FL
14	1		*FRONT RIGHT SIDE DOOR TOP HINGE	Repair	45.00 F	*- FL
15	1		*FRONT RIGHT SIDE DOOR LOWER HINGE	Repair	42.00 F	*- FL
16	1		*FRONT RIGHT SIDE DOOR STOPPER	Serviceable	8.00 F	*- FL
17	1		*FRONT RIGHT SIDE DOOR OUTER MIRROR ASSY	Dented / Cut	726.00 F	*726.00 FL
18	1		*REAR RIGHT SIDE DOOR	Bent	1,050.00 F	*1,050.00 FL
19	1		*REAR RIGHT SIDE DOOR VERTICAL BLACK STICKER	Necessary	68.00 F	*68.00 FL
20	1		*REAR RIGHT SIDE DOOR HORIZONTAL BLACK STICKER	Necessary	81.00 F	*81.00 FL
21	1		*REAR RIGHT SIDE TYRE RIM	Serviceable	483.00 F	*- FL
22	1		*REAR RIGHT SIDE DOOR CHROME PROTECTOR (UPPER)	Serviceable	81.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,295.20	3,652.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	730.54
Total Parts (\$\$)	6,295.20	2,922.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED	New	150.00	90.00
2	STRAIGHTENING ,REPAIRING AND REALIGNING ON VEHICLE RIGHT SIDE PORTION ,CUTTING FRONT RIGHT SIDE FENDER ,KNOCKING RIGHT SIDE REAR FENDER ,DISMANTLE AND REPLACE THE ABOVE MENTIONED PARTS	New	1,200.00	750.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED PANELS,FRONT RIGHT SIDE FENDER ,FRONT RIGHT SIDE DOOR ,REAR RIGHT SIDE DOOR AND REAR RIGHT SIDE FENDER	New	1,200.00	1,000.00
4	TO TRANSFER DOOR MECHANISM (F&R DOOR) INTO NEW DOOR PANEL	New	300.00	120.00
Gross Labour Cost (\$)			2,850.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >