



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 9090R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	1,500.00	1,466.00
1	FRONT HEADLAMP LH	NOT NECESSARY	1,100.00	-
	LESS 10% DISCOUNT		-260.00	-146.60
			2,340.00	1,319.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT GRILLE (SN)	BROKEN	800.00	700.00
1	FRONT GRILLE MERCEDES LOGO CHROME (SN)	BROKEN	200.00	150.00
			1,000.00	850.00
	<u>LABOUR</u>			
	SPRAY PAINTING TO FACILITATE REPAIR .		500.00	200.00
	PANEL BEATING TO FACILITATE REPAIR .		500.00	200.00
			1,000.00	400.00
	GRAND TOTAL		4,340.00	2,569.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/SMO22007348/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.