

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22007349/GVY3Q2**Date:** 29/09/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001539		
Claimant Vehicle No :	SHA1618L	Insured Vehicle No :	GBH9067H		
Date of Loss:	01/08/2022	Nature of Claim:	TP	Claim No:	M2204044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1618L	Engine No:	D4DFDU502259
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU097268
Reg. Date:	22/12/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,925.68	941.76	1,983.92	67.81
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,260.00	780.00	480.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,196.68	1,732.76	2,463.92	58.71
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	4,196.68	1,350.00	2,846.68	67.83
+ GST 7.00/7.00% (S\$)	293.77	94.50	199.27	67.83
Nett Amount (S\$)	4,490.45	1,444.50	3,045.95	67.83

INSPECTION

Date of Assignment:	02/08/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/08/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Sep 2022)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1618L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	44.80 FL	*- FL
3	1		*FRONT BUMPER GRILLE LH	Not Necessary	187.20 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*FRONT FENDER LH	Repair	663.00 FL	*- FL
6	1		*FRONT FENDER SHIELD LH	Not Necessary	174.90 FL	*- FL
7	1		*HEADLAMP LH	Not Necessary	1,388.00 FL	*- FL
8	1		*FRONT FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,632.10	1,152.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	706.42	210.44
Total Parts (\$\$)	2,925.68	941.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK LIGHTING FRONT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,260.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >