

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007350/UVY3Q2**Date:** 11/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00196642100

**Claimant Vehicle
No :** SMU4180Y**Insured Vehicle
No :** SKW3485M

Date of Loss: 27/07/2022

Nature of Claim: TP

Claim
No: SNM22D205265/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMU4180Y**

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HR16930106C

Reg. Date: 23/08/2018 (Man. Year: 2018)

Chassis No: MNTBBAB17Z0032715

Colour: Blue

Odometer: 103340 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,969.61	2,853.62	15,115.99	84.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	930.00	3,100.00	76.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,999.61	3,783.62	18,215.99	82.80
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	21,999.61	3,000.00	18,999.61	86.36

INSPECTION

Date of Assignment: 10/08/2022

Date Inspected: 29/07/2022 Inspected At:

Euro Success Services Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
Parts:	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4180Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP L/H	Scratched	1,050.00 FN	*815.00 FN
2	1		*FRONT HEADLAMP R/H	Scratched	1,050.00 FN	*815.00 FN
3	1		*FRONT HEADLAMP BRACKET	Not Necessary	45.00 FN	*- FN
4	1		*FRONT BONNET	Not Necessary	725.00 FN	*- FN
5	2		*FRONT BONNET HANGER	Not Necessary	379.80 FN	*- FN
6	1		*FRONT SUPPORT PANEL	Repair	480.20 FN	*- FN
7	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	250.75 FN	*- FN
8	1		*FRONT SUPPORT PANEL CENTRE BRACKET	Not Necessary	154.80 FN	*- FN
9	1		*FRONT GRILLE	Cracked	350.60 FN	*348.00 FN
10	1		*FRONT GRILLE MOULDING	Not Necessary	185.00 FN	*- FN
11	1		*FRONT FENDER L/H	Repair	498.90 FN	*- FN
12	1		*FRONT FENDER INNER SHIELD L/H	Torn	220.50 FN	*148.50 FN
13	1		*FRONT BUMPER	Distorted	798.50 FN	*579.90 FN
14	1		*FRONT BUMPER LOWER COVER	Torn	65.50 FN	*65.50 FN
15	1		*FRONT BUMPER REINFORCEMENT	Repair	520.00 FN	*- FN
16	1		*FRONT BUMPER SPONGE	Torn	350.50 FN	*128.90 FN
17	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	120.90 FN	*- FN
18	1		*FRONT BUMPER BRACKET L/H	Not Necessary	65.00 FN	*- FN
19	2		*FRONT BUMPER RETAINERS	Bent	75.80 FN	*75.80 FN
20	1		*FRONT BUMPER LOWER PAD KIT	Not Necessary	450.00 FN	*- FN
21	1		*FRONT SPRT LIGHT L/H	Not Necessary	28.80 FN	*- FN
22	1		*FRONT SPRT LIGHT COVER L/H	Not Necessary	60.90 FN	*- FN
23	1		*FRONT SPRT LIGHT CHROME GRILL L/H	Scratched	180.90 FN	*105.20 FN
24	1		*AIR CON CONDENSER	Not Necessary	985.50 FN	*- FN
25	1		*AIR CLEANER INTAKE DUCT	Not Necessary	130.40 FN	*- FN
26	1		*AIR CLEANER BOX	Not Necessary	300.00 FN	*- FN
27	1		*AIR CLEANER RESONATOR	Not Necessary	195.60 FN	*- FN
28	2		*AIR CON PIPE	Not Necessary	379.20 FN	*- FN
29	1		*AIR CON DISCHARGE PIPE	Not Necessary	410.70 FN	*- FN
30	1		*AIR CON SUCTION PIPE	Not Necessary	415.60 FN	*- FN
31	1		*AIR CON LIQUID PIPE	Not Necessary	318.50 FN	*- FN
32	1		*AIR FILTER BOX	Not Necessary	350.50 FN	*- FN
33	1		*AIR FILTER HOUSE	Not Necessary	265.50 FN	*- FN
34	1		*AIR FILTER DUCT	Not Necessary	125.60 FN	*- FN
35	1		*AIR FILTER LOWER BOX	Not Necessary	245.00 FN	*- FN
36	1		*RADIATOR ASSY	Not Necessary	1,520.60 FN	*- FN
37	1		*RADIATOR TOP HOSE	Not Necessary	90.60 FN	*- FN
38	2		*RADIATOR TOP MOUNTING	Not Necessary	65.20 FN	*- FN
39	1		*RADIATOR BOTTOM HOSE	Not Necessary	95.60 FN	*- FN
40	1		*RADIATOR ELECTRIC FAN ASSY	Not Necessary	620.30 FN	*- FN
41	1		*RADIATOR SPARE TANK	Not Necessary	145.10 FN	*- FN
42	1		*RADIATOR	Not Necessary	1,278.10 FN	*- FN
43	1		*FRONT DOOR SIDE MIRROR L/H	Not Necessary	695.50 FN	*- FN
44	1		*FRON SHOCK ABSORBER L/H	Not Necessary	452.80 FN	*- FN
45	1		*FRONT KNUCL ARM L/H	Not Necessary	623.50 FN	*- FN
46	1		*FRONT WHEEL BEARING L/H	Not Necessary	355.80 FN	*- FN

Report was unsubmitted during this print-out.

8/11/22, 1:40 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LOWER ARM L/H	Not Necessary	439.80 FN	*- FN
48	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
49	1		*FRONT FENDER INNER SHIELD CLIPS L/H	Necessary	45.50 FS	*40.00 FS
50	1		*FRONT SPORT RIMS L/H	Repair	802.50 FS	*- FS
51	1		*FRONT TYRE L/H	Serviceable	320.50 FS	*- FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					19,830.85	3,161.80
- Nett Item Discount on N Items 10.00/10.00% (\$\$)					1,861.24	308.18
Total Parts (\$\$)					17,969.61	2,853.62
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT AIR CON COMPRESSOR AND RADIATOR TOP UP	New	80.00	0.00
2	TO CHECK FRONT & REAR WIRING ,LIGHTING AND RESETTING	New	150.00	20.00
3	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	300.00	0.00
4	TO APPLY UNDERCOATING ON REPAIR AND REPLACE PANEL	New	350.00	0.00
5	TO PROVIDE LABOUR CHARGE ,WORKMANSHIP TO DISMANTLE ABOVE MENTION PARTS ,REPAIRS INCLUSIVE OF CUT & WELD ,REALIGN BODY STRUCTURE AND DAMAGED CAUSD BY ACCIDENT	New	1,500.00	300.00
6	TO RESPRAY PAINT INCLUDING POLISH & WAXING ON ACCIDENT PORTION	New	1,500.00	550.00
7	TO CHECK WHEEL ALIGNMENT	New	150.00	60.00
Gross Labour Cost (\$\$)			4,030.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >