

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007351/KCY3Q2**Date:** 22/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00073522106

Claimant Vehicle No : SLC9421B **Insured Vehicle No :** YN8563U

Date of Loss: 26/07/2022 Nature of Claim: TP Claim No: SNM22D205217/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC9421B**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4037508

Reg. Date: 30/05/2016 (Man. Year: 2016) Chassis No: RU11117505

Colour: Metallic Blue Odometer: 121306 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18

Front Left Side: Rotalla 7 mm Rear Left Side: Rotalla 7 mm

Front Right Side: Rotalla 7 mm Rear Right Side: Rotalla 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,211.00	2,962.40	2,248.60	43.15
Miscellaneous Items	1,415.00	875.00	540.00	38.16
Labour	3,090.00	2,440.00	650.00	21.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,716.00	6,277.40	3,438.60	35.39
Approved Total (Overridden) (\$\$)		5,650.00		
(\$\$)	9,716.00	5,650.00	4,066.00	41.85
+ GST 7.00/7.00% (\$\$)	680.12	395.50	284.62	41.85
Nett Amount (\$\$)	10,396.12	6,045.50	4,350.62	41.85

INSPECTION

Date of Assignment: 02/08/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 29/07/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9421B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	180.00 F	*180.00 FL
2	1		*1 PC REAR BUMPER LOWER UNDER COVER	Cracked	75.00 F	*75.00 FL
3	1		*6 PCS REAR BUMPER LOWER UNDER COVER CLIPS @2/PC	Necessary	12.00 F	*12.00 FL
4	1		*1 PC REAR BUMPER LH SIDE PAD	Buckled	68.00 F	*68.00 FL
5	1		*1 PC REAR BUMPER LH RETAINER	Distorted	12.00 F	*12.00 FL
6	1		*1 PC REAR BUMPER LH REFLECTOR	Cracked	40.00 F	*40.00 FL
7	1		*1 PC REAR BUMPER RH REFLECTOR	Serviceable	40.00 F	*- FL
8	1		*1 PC REAR RH FENDER WHEEL ARCH TRIM	Serviceable	55.00 F	*- FL
9	1		*1 PC TAILGATE	Bent	570.00 F	*570.00 FL
10	1		*2 PCS TAILGATE DAMPER STRUT @90/PC	Serviceable	180.00 F	*- FL
11	1		*1 PC TAILGATE EMBLEM (VEZEL)	Necessary	35.00 F	*35.00 FL
12	1		*1 PC TAILGATE OUTER GARNISH	Cracked	125.00 F	*125.00 FL
13	1		*1 PC TAILGATE OUTER GARNISH EMBLEM (H)	Necessary	15.00 F	*15.00 FL
14	1		*1 PC TAILGATE REFLECTOR LH	Cracked	138.00 F	*138.00 FL
15	1		*1 PC TAILGATE REFLECTOR RH	Cracked	138.00 F	*138.00 FL
16	1		*1 PC TAILGATE INNER TRIM BOARD	Cracked	105.00 F	*105.00 FL
17	1		*1 PC TAILGATE INNER TRIM BOARD LH UPPER	Serviceable	25.00 F	*- FL
18	1		*1 PC TAILGATE INNER TRIM BOARD RH UPPER	Serviceable	25.00 F	*- FL
19	1		*1 PC TAILGATE INNER PULL POCKET	Dented	20.00 F	*20.00 FL
20	1		*1 PC TAILGATE INNER LOCK	Jammed	75.00 F	*75.00 FL
21	1		*1 PC LH TAILLAMP	Cracked	270.00 F	*270.00 FL
22	1		*1 PC RH TAILLAMP	Cut	270.00 F	*270.00 FL
23	1		*1 PC 3RD BRAKE LAMP	Serviceable	130.00 F	*- FL
24	1		*1 PC REAR NUMBER PLATE LAMP	Serviceable	20.00 F	*- FL
25	1		*1 PC SPARE TYRE PANEL	Bent	490.00 F	*490.00 FL
26	1		*1 PC SPARE TYRE TOP COVER BOARD	Serviceable	155.00 F	*- FL
27	1		*1 PC REAR FENDER INNER TRIM LH	Serviceable	185.00 F	*- FL
28	1		*1 PC REAR FENDER INNER TRIM RH	Serviceable	185.00 F	*- FL
29	1		*10 PCS REAR FENDER INNER TRIM CLIPS @2/PC	Not Necessary	20.00 F	*- FL
30	1		*1 PC REAR END PANEL	Bent	290.00 F	*290.00 FL
31	1		*1 PC REAR END PANEL INNER TRIM	Dented	55.00 F	*55.00 FL
32	1		*1 PC REAR WIPER ARM	Missing	45.00 F	*45.00 FL
33	1		*1 PC REAR WIPER ARM COVER	Missing	8.00 F	*8.00 FL
34	1		*1 PC REAR WIPER BLADE	Missing	42.00 F	*42.00 FL
35	1		*1 PC REAR WIPER MOTOR	Bent	115.00 F	*115.00 FL
36	1		*1 PC REAR EXHAUST MUFFLER	Repair	370.00 F	*- FL
37	1		*1 PC REAR EXHAUST MOUNTING	Serviceable	13.00 F	*- FL
38	1		*1 PC REAR TOOL BOX TRAY	Serviceable	105.00 F	*- FL
39	1		*1 PC REAR WINDSCREEN GLASS	Shattered	450.00 F	*450.00 FL
40	1		*1 SET REAR WINDSCREEN GLASS MOULDING	Necessary	60.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,211.00	3,703.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	740.60
Total Parts (\$\$)	5,211.00	2,962.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REAR BUMPER LOWER SKIRT EXTENSION Missing	250.00	250.00
2	1	1 PC REAR CAMERA Serviceable	320.00	0.00
3	1	1 PC REAR FLOOR RUBBER TRAY Serviceable	220.00	0.00
4	1	1 PC REAR NUMBER PLATE Dented	35.00	35.00
5	1	1 PC REAR WINDSCREEN GLASS SEALANT Necessary	40.00	40.00
6	1	1 SET REVERSE CAMERA Shorted	350.00	350.00
7	1	1 SET REVERSE SENSOR Dented	200.00	200.00
Sub Total (\$\$)			1,415.00	875.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX SEAT ASSY,CARPET,GARNISH, TOP ROOF LINING AND WASH CUSHION	New	120.00	100.00
4	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER ASSY, LOCK ASSY, TOP SPOILER, LOWER SKIRT, TO CUT, WELD & RENEW REAR END PANEL, REAR COMPARTMENT, TO STRAIGHTEN, KNOCK & REPAIR REAR BOTH CHASSISS, REAR BOTH FENDERS AND REALIGN THE SAME	New	1,300.00	1,000.00
5	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	60.00	60.00
6	PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOTH FENDERS, TAILGATE, REAR COMPARTMENT	New	1,300.00	1,000.00
7	REMOVE & REFIX REAR SENSORS, REVERSE CAMERA, CCTV CAMERA, SMART KEY AND RESET SYSTEM	New	50.00	50.00
8	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (\$\$)			3,090.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >