

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS/AIS22007354/KVY3Q2**Date:** 15/09/2022**REFERENCE**

Insured/Claimant:	SIM CHUN WEI	Policy No:	SP2001875801-01	
Date of Loss:	29/07/2022	Nature of Claim:	OD	Claim No: 202222005907SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKW8560X</b>		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB633915
Reg. Date:	18/11/2015 (Man. Year: 2015)	Chassis No:	ZSU600056728
Colour:	Metallic Black	Odometer:	91077 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,996.50	770.00	1,226.50	61.43
Miscellaneous Items	66.00	66.00	0.00	0.00
Labour	2,090.00	1,800.00	290.00	13.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,152.50</b>	<b>2,636.00</b>	<b>1,516.50</b>	<b>36.52</b>
<b>- Excess (S\$)</b>	0.00	600.00	-600.00	
<b>(S\$)</b>	4,152.50	2,036.00	2,116.50	50.97
<b>+ GST 7.00/7.00% (S\$)</b>	290.68	142.52	148.16	50.97
<b>Nett Amount (S\$)</b>	<b>4,443.18</b>	<b>2,178.52</b>	<b>2,264.66</b>	<b>50.97</b>

**INSPECTION**

Date of Assignment:	02/08/2022	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	02/08/2022	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days		

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW8560X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT WINDSCREEN GLASS WITH MOULDING (WCP)	Cracked	700.00 F	*700.00 F
2	1		*1 PC LH DOOR SIDE MIRROR (WCP)	Serviceable	320.00 F	*- F
3	1		*1 PC LH DOOR SIDE MIRROR COVER (WCP)	Serviceable	45.00 F	*- F
4	1		*1 PC DASHBOARD (WCP)	Serviceable	750.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					1,815.00	700.00
+ Margin on L,N Items 10.00/10.00% (S\$)					181.50	70.00
Total Parts (S\$)					1,996.50	770.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 PC ERP BRACKET (NECESSARY)	26.00	26.00
2	1	1 PC FRT WINDSCREEN GLASS SEALANT (NECESSARY)	40.00	40.00
Sub Total (\$\$)			66.00	66.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FRT WINDSCREEN GLASS	New	100.00	100.00
2	REPAIR LH FRONT W/SCREEN PILLAR,BONNET,LH FRONT FENDER AND REALIGN THE SAME	New	650.00	550.00
3	PUTTY & RESPRAY ON BINNET,FRT LH FENDER,SIDE MIRROR,COVER,LH W/SCREEN PILLAR, TOP ROOF PANEL	New	980.00	850.00
4	REMOVE & REFIX DASHBOARD	New	280.00	250.00
5	TO VACUUM & CLEAN UP GLASS SPLINTERS	New	80.00	50.00
Gross Labour Cost (\$\$)			2,090.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >