

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY Code: ASM Policy Particulars:- (THIRD PARTY CLAIM) Insured Veh. SGS 898T Veh. Inspected SME 6146T Policy No. P1483597 Coverage (\$) 0.00 Claim No. S2M047ZE Excess (\$) 0.00 Assign From TEO KITTY Assign Date CS3/ASM22007358/Tqy3 Ref: CS3/ASM22007358/Tqy3 28/09/2022	8m4	
SINGAPORE 068811		
Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SGS 898T Veh. Inspected SME 6146T Policy No. P1483597 Coverage (\$) 0.00 Claim No. S2M047ZE Excess (\$) 0.00 Assign From TEO KITTY Assign Date 02/08/2022		
Insured Veh. SGS 898T Veh. Inspected SME 6146T		
Policy No. P1483597 Coverage (\$) 0.00 Claim No. S2M047ZE Excess (\$) 0.00 Assign From TEO KITTY Assign Date 02/08/2022		
Claim No. S2M047ZE Excess (\$) 0.00 Assign From TEO KITTY Assign Date 02/08/2022		
Assign From TEO KITTY Assign Date 02/08/2022		
2. Vehicle Particulars & Condition		
Make & Model HONDA VEZEL c.c 1496		
Engine No. HIDDEN Year of Reg. 2018		
Chassis No. RU31268950 Colour SILVER		
Odometer 187408 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 215/60 R16 DUNLOP 6 mm		
L/H Front Tyre 215/60 R16 DUNLOP 6 mm		
R/H Rear Tyre 215/60 R16 DUNLOP 6 mm		
L/H Rear Tyre 215/60 R16 DUNLOP 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.		
5. General Information		
Accident Date 30/07/2022 Inspect Date / Time 02/08/2022 (03:00 PM)		
Survey held at 365 AUTOMOTIVE PTE LTD		
25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @KB SINGAPORE 417800		
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,00	0	
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days		

Report Ref No. CS3/ASM22007358/Tqy3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.