



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFF 8073J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	758.40	455.10
2	REAR BUMPER SIDE RETAINER	NECESSARY	130.00	130.00
2	REAR BUMPER SIDE BRACKET	NOT NECESSARY	156.00	-
2	REAR BUMPER LOWER SIDE GARNISH	NOT NECESSARY	336.00	-
1	REAR BUMPER CLIPS	NECESSARY	60.00	48.00
1	REAR BOOTLID PANEL	TO REPAIR SEE LABOUR	799.40	-
1	REAR BOOTLID INNER LOCK	NOT NECESSARY	195.80	-
1	REAR BOOTLID CATCH	NOT NECESSARY	58.70	-
1	REAR TAILLAMP	NOT NECESSARY	725.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	687.20	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	165.80	-
1	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
1	REAR LEFT FENDER	NOT NECESSARY	1,012.30	-
	LESS 25% DISCOUNT		-1,286.35	-158.28
			3,859.05	474.82
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILLAMP PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE W/BASE GARNISH (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			500.00	-
<u>LABOUR</u>				
	TO REMOVE, REPLACE DAMAGED LAMPS & CHECK UP WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES TO ASSIST REPAIR.		150.00	60.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOTLID PANEL AND REAR END PANEL. TO RE-SPRAY THE AFFECTED AREAS.		700.00	450.00
			800.00	600.00
			2,080.00	1,180.00
GRAND TOTAL			6,439.05	1,654.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,300.00

Report Ref No. CS/INC22007368/Ucy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.