

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 270Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	899.70	-
1	REAR BUMPER SIDE HOLDER	NOT NECESSARY	48.50	-
1	REAR SIDE PANEL LH	TO REPAIR SEE LABOUR	5,699.50	-
1	REAR SIDE PANEL WHEEL HOUSE	NOT NECESSARY	367.70	-
	LESS 30% DISCOUNT		-2,104.62	-
			4,910.78	-
	NETT ITEMS			
1	REAR SIDE PANEL AIR VENT (N)	NOT NECESSARY	68.50	-
1	REAR MUDFLAP (N)	NOT NECESSARY	125.00	-
1	REAR WHEEL RIM (N)	NOT NECESSARY	310.70	-
	LESS 10% DISCOUNT		-50.42	-
			453.78	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE, REPLACE DAMAGED LAMPS & CHECK UP WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT INNER GARNISHES TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.	NOT NECESSARY	200.00	-
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR SIDE PANEL LH.		600.00	100.00
	TO RE-SPRAY THE AFFECTED AREAS.		700.00	400.00
			1,730.00	500.00
	GRAND TOTAL		7,154.56	500.00

Report Ref No. CS/INC22007369/Uvy3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		500.00
(CONFIRMED)		

Report Ref No. CS/INC22007369/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser