

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 4281T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR ASSEMBLY LH	CRACKED	3,562.00	3,562.00
1	RECORDING CAMERA (NPA)	* CHECK	-	-
1	ROOF UPPER MIRROR LH	CRACKED	680.00	680.00
1	FRONT WINDSCREEN	* CHECK	3,350.00	-
1	WINDSCREEN RUBBER	* CHECK	395.60	-
1	IU BRACKET	* CHECK	40.00	-
1	BODY STICKER	NOT NECESSARY	150.00	-
6	WINDSCREEN SEALANT @\$45.00	* CHECK	270.00	-
			8,447.60	4,242.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE AND CHECK WIRE HARNESS.		800.00	300.00
	LABOUR TO REMOVE,REPAIR AND REINSTALL FRT DOOR LH, SIDE MIRROR ASSEMBLY LH, ROOF TOP MIRROR LH.		2,000.00	500.00
	LABOUR TO REMOVE AND REINSTALL FRT WINDSCREEN.	* CHECK	800.00	-
	LABOUR TO RESPRAY FRT DOOR LH, AND ROOF TOP.	NOT NECESSARY	1,500.00	-
	LABOUR TO CARRY OUT DIAGNOSTIC CHECK.		350.00	100.00
			5,450.00	900.00
	GRAND TOTAL		13,897.60	5,142.00
	DECOMMENDED COST OF DEDAIDS			F 4 40 00

RECOMMENDED COST OF REPAIRS		5,142.00
(REPAIR COST NOT CONCLUDE)		·
(EXCLUDE CHECK ITEMS S\$4,855.60 NETT)		

Report Ref No. CS/FCI22007370/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X: 2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.