

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007373/KNY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00003712200		
<b>Claimant Vehicle No :</b>	SLR9545Z	<b>Insured Vehicle No :</b>	SMP1161Z		
Date of Loss:	30/07/2022	Nature of Claim:	TP	Claim No:	SNM22D205368/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLR9545Z</b>		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRB853280
Reg. Date:	31/08/2017 (Man. Year: 2016)	Chassis No:	ZSU600086133
Colour:	Metallic Black	Odometer:	74750 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,908.30	4,091.85	6,816.45	62.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,380.00	2,050.00	59.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,338.30</b>	<b>5,471.85</b>	<b>8,866.45</b>	<b>61.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,338.30</b>	<b>4,350.00</b>	<b>9,988.30</b>	<b>69.66</b>

**INSPECTION**

Date of Assignment:	02/08/2022	
Date Inspected:	02/08/2022 Inspected At:	SQM PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Sep 2022)	
<b>Parts:</b>	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR9545Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,885.00 FL	*1,466.10 FL
2	2		*TAILGATE LAMPS	Serviceable	580.00 FL	*- FL
3	1		*TAILGATE TRIM BOARD	Mtg Cracked	788.60 FL	*578.00 FL
4	1		*TAILGATE LOCK	Dented	560.00 FL	*418.00 FL
5	1		*TAILGATE LOCK LATCH	Repair	68.00 FL	*- FL
6	1		*TAILGATE LOCK LOWER SENSOR	Cracked	385.00 FL	*185.00 FL
7	1		*TAILGATE WEATHERSTRIP (50%)	Distorted / Dented	257.85 FS	*171.90 FS
8	2		*TAILLAMPS	Serviceable	1,564.00 FL	*- FL
9	2		*TAILLAMP PANELS	Repair	440.00 FL	*- FL
10	2		*TAILLAMP LOWER BRACKETS	Serviceable	280.00 FL	*- FL
11	1		*REAR W/SCREEN MOULDING	Necessary	220.00 FL	*190.50 FL
12	1		*HARRIER EMBLEMS	Necessary	98.00 FL	*98.00 FL
13	1		*TAILGATE CENTER LOGO	Necessary	120.00 FL	*66.00 FL
14	1		*END PANEL	Repair	850.00 FL	*- FL
15	1		*END PANEL TOP GARNISH	Mtg Cracked	445.00 FL	*361.00 FL
16	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
17	1		*REAR BUMPER	Buckled	1,685.00 FL	*866.00 FL
18	2		*REAR BUMPER BRACKETS	Repair	220.00 FL	*- FL
19	2		*REAR BUMPER RETAINERS	Serviceable	280.00 FL	*- FL
20	1		*REAR BUMPER LOWER GARNISH	Bent	980.00 FL	*419.00 FL
21	2		*REAR BUMPER REFLECTORS	Serviceable	330.00 FL	*- FL
22	1		*REAR BUMPER SPONGE	Cracked	354.00 FL	*199.00 FL
23	1		*REAR BUMPER BEAM	No such part	448.00 FL	*- FL
24	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
25	2		*T REAR W/SCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
26	1		*SET REAR BUMPER SENSORS	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>14,303.45</b>	<b>5,303.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	3,395.15	1,211.65
<b>Total Parts (\$)</b>	<b>10,908.30</b>	<b>4,091.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE TO REPAIR ,REPLACE ,ALIGN ADJUST ,REMOVE & REFIX ACCIDENT AFFECTED AREA	New	1,400.00	500.00
2	TO DO ANTI RUST	New	120.00	30.00
3	TO CHECK WIRING SYSTEM REPLACE SENSORS	New	150.00	70.00
4	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE	New	140.00	60.00
5	TRANSFER REAR W/SCREEN	New	140.00	120.00
6	TO DO SPRAY PAINTING	New	1,200.00	600.00
7	TO DO COMPUTER SETTING ,DIGANOSE DELETE FAULT CODE AFTER REPAIR (RESET AUTO TAILGATE AFTER REPAIR)	New	280.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>3,430.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >