

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007375/KVY3Q2**Date:** 14/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00256822100
Claimant Vehicle No :	SMX1849G	Insured Vehicle No :	SKF4867C
Date of Loss:	29/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205326/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1849G	Engine No:	R16B21601527
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650GT001228
Reg. Date:	10/02/2017 (Man. Year: 2016)	Odometer:	91032 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Maxxis 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Maxxis 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,241.68	1,241.68	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	900.00	550.00	37.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,691.68	2,141.68	550.00	20.43
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	2,691.68	1,700.00	991.68	36.84
+ GST 7.00/7.00% (\$\$)	188.42	119.00	69.42	36.84
Nett Amount (\$\$)	2,880.10	1,819.00	1,061.10	36.84

INSPECTION

Date of Assignment:	19/08/2022	176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE
Date Inspected:	04/08/2022 Inspected At:	SINGAPORE 575721
		Repairer: Falcon-air Auto Services Pte Ltd (pandan Loop) (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX1849G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	617.50 FL	*617.50 FL
2	1		*REAR BUMPER LOWER	Dented	70.00 FL	*70.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	235.00 FL	*235.00 FL
4	1		*BOOT COVER	Bent	554.60 FL	*554.60 FL
5	1		*SET ASSORTED CLIPS	Necessary	60.00 FS	*60.00 FS
					Sub Total (\$\$)	1,537.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	295.42
					Total Parts (\$\$)	1,241.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REFIX BOOT COVER MECHANISM	New	100.00	50.00
2	TO REMOVE /REFIT REVERSE SENSOR INTO NEW BUMPER	New	50.00	50.00
3	TO REPAIR REAR END PANEL INCLUDING REPLACEMENT OF PARTS	New	550.00	400.00
4	TO SPRAY PAINT ON BOOT COVER ,REAR BUMPER ,REAR END PANEL	New	750.00	400.00
Gross Labour Cost (S\$)			1,450.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >