

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22007378/EQY3Q2**Date:** 01/11/2022**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMN5375H **Insured Vehicle No :** SJC9472C

Date of Loss: 27/07/2022 Nature of Claim: TP Claim No: DMPC2200316H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN5375H**

Make & Model: SUZUKI JIMNY, 1.5 GLX AT (A) Engine No: K15B1028692

Reg. Date: 16/08/2019 (Man. Year: 2019) Chassis No: JSAGJB74V00116713

Colour: Green Odometer: 63274 km

Engine Capacity: 1462 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 3,828.25 | 3,478.00 | 350.25 | 9.15 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,283.50 | 3,245.50 | 2,038.00 | 38.57 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,111.75 | 6,723.50 | 2,388.25 | 26.21 |
| + GST 7.00/7.00% (S\$) | 637.82 | 470.65 | 167.17 | 26.21 |
| Nett Amount (S\$) | 9,749.57 | 7,194.15 | 2,555.42 | 26.21 |

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 10/08/2022 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 01 Nov 2022) |
| Parts: | 192 | SUZUKI JIMNY 1.5 GLX AT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMN5375H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 100.00 FS | *50.00 FS |
| 2 | 1 | | *HEADLAMP ASSY ,R | Cracked | 1,242.15 FS | *1,242.15 FS |
| 3 | 1 | | *LAMP ASSY ,FOG AND DRL | Cut | 216.55 FS | *216.55 FS |
| 4 | 1 | | *BRACKET ,FOG LAMP R | Not Necessary | 36.30 FS | *- FS |
| 5 | 1 | | *PANEL FR OUTER | Dented | 505.65 FS | *505.65 FS |
| 6 | 1 | | *SHROUD RADIATOR UPR | Not Necessary | 60.50 FS | *- FS |
| 7 | 1 | | *MEMBER COMP 1ST MOUNT | Not Necessary | 55.00 FS | *- FS |
| 8 | 1 | | *MEMBER LAMP SUPPORT ,R | Not Necessary | 23.10 FS | *- FS |
| 9 | 1 | | *PANEL COMP 1ST MOUNT R | Not Necessary | 98.95 FS | *- FS |
| 10 | 1 | | *PANEL ,FR FENDER R | Dented | 142.95 FS | *142.95 FS |
| 11 | 1 | | *LINING COMP FRONT FENDER ,R | Torn | 60.50 FS | *60.50 FS |
| 12 | 1 | | *BUMPER ,FRONT | Broken | 450.70 FS | *450.70 FS |
| 13 | 1 | | *GRILLE RADIATOR | Broken | 313.30 FS | *313.30 FS |
| 14 | 1 | | *NET ,FRONT BUMPER | Broken | 34.65 FS | *34.65 FS |
| 15 | 1 | | *GARNISH ,FR BPR LICENSE (BLACK) | Broken | 39.60 FS | *39.60 FS |
| 16 | 1 | | *SKIRT ,FR AIR DAM | Not Necessary | 26.40 FS | *- FS |
| 17 | 1 | | *GUARD FR FNDR SPLASH R (BLACK) | Crushed | 107.20 FS | *107.20 FS |
| 18 | 1 | | *PROTECTOR FR FENDER SPLASH | Necessary | 20.35 FS | *20.35 FS |
| 19 | 1 | | *BOLT ,1ST MOUNTING | Necessary | 4.65 FS | *4.65 FS |
| 20 | 1 | | *HOSE ASSY ,HEADLAMP CLEANERNO2 | Broken | 151.70 FS | *151.70 FS |
| 21 | 1 | | *CASE ASSY ,HEADLAMP CLEANER | Broken | 13.40 FS | *13.40 FS |
| 22 | 1 | | *BRACKET ,FOG LAMP ,R | Broken | 36.30 FS | *36.30 FS |
| 23 | 1 | | *SHROUD RADIATOR LWR | Broken | 71.50 FS | *71.50 FS |
| 24 | 1 | | *COVER ,RELAY BOX | Broken | 16.85 FS | *16.85 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,828.25** **3,478.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | SUPPLY NUMBER PLATE | New | 80.00 | 80.00 |
| 2 | RESET AND REPROGRAMME ECU | New | 146.50 | 146.50 |
| 3 | REPLACE AND REFOCUS HEADLAMP | New | 293.00 | 293.00 |
| 4 | REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE REPAIR ,STRAIGHTEN FRT BUMPER ,R/F FENDER ,FRT SUPPORT PANEL ,R/F DOOR AND AFFECTED PORTION OF CAR | New | 2,344.00 | 1,758.00 |
| 5 | SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR | New | 2,420.00 | 968.00 |
| Gross Labour Cost (\$\$) | | | 5,283.50 | 3,245.50 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >