

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122007379/KVY3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMC9359L **Insured Vehicle No :** SLM5621P

Date of Loss: 31/07/2022 Nature of Claim: TP Claim No: CDMPG22001543

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC9359L**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: G4LCJU023122

Reg. Date: 28/07/2018 (Man. Year: 2018) Chassis No: KMHCU41BT KU440156

Colour: Metallic Red Odometer: 54017 km

Engine Capacity: 1368 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/75 R14 Rear Tyre Size: 175/75 R14

Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,972.20	405.30	1,566.90	79.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	930.00	770.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,672.20	1,335.30	2,336.90	63.64
+ GST 8.00/8.00% (S\$)	293.78	106.82	186.96	63.64
Nett Amount (S\$)	3,965.98	1,442.12	2,523.86	63.64

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 03/08/2022 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Apr 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC9359L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Buckled / Dented	265.00 F	*265.00 F
2	1		*REAR BUMPER SIDE BRACKET LH (WCP)	Distorted	23.00 F	*23.00 F
3	1		*REAR BUMPER REFLECTOR LH (WCP)	Scratched	35.00 F	*35.00 F
4	1		*REAR BUMPER REINFORCEMENT (WCP)	Repair	210.00 F	*- F
5	1		*REAR TAIL LAMP LH (WCP)	Serviceable	210.00 F	*- F
6	1		*REAR FENDER LH (WCP)	Repair	590.00 F	*- F
7	1		*REAR FENDER AIR VENT LH (WCP)	Serviceable	24.00 F	*- F
8	1		*REAR WINDSCREEN MOULDING (WCP)	Not Necessary	45.00 F	*- F
9	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
10	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
11	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
						F=Franchise part. S=SpcNett.
					Sub Total (S\$)	1,832.00 373.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	140.20 32.30
					Total Parts (S\$)	1,972.20 405.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR FENDER LH & ETC	New	500.00	400.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR FENDER LH	New	150.00	0.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
5	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLSTERY CUSHION SET & ETC .TO EFFECT REPLACE OF REAR FENDER LH	New	250.00	60.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS & ETC	New	120.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
Gross Labour Cost (\$\$)			1,700.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >