

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22007381/ANY3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKT8366G**Insured Vehicle No :** GBG2610R

Date of Loss: 01/08/2022

Nature of Claim: TP

Claim No: CDMCG22001552

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKT8366G**

Make & Model: TOYOTA COROLLA, 1.5 (A)

Engine No: 1ZR512580

Reg. Date: 09/06/2015 (Man. Year: 2015)

Chassis No: MR053REH104533570

Colour: Silver

Odometer: 38918 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,697.15	2,475.25	2,221.90	47.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,010.00	830.00	45.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,537.15	3,485.25	3,051.90	46.69
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	6,537.15	2,700.00	3,837.15	58.70
+ GST 7.00/7.00% (S\$)	457.60	189.00	268.60	58.70
Nett Amount (S\$)	6,994.75	2,889.00	4,105.75	58.70

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 03/08/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2022)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT8366G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	671.20 FL	*556.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
4	1		*REAR BUMPER ENFOCEMENT	Not Necessary	251.40 FL	*- FL
5	1		*REAR BUMPER SPONGE	Not Necessary	142.80 FL	*- FL
6	1		*REAR BUMPER O/S REFLECTOR	Not Necessary	95.40 FL	*- FL
7	1		*REAR BUMPER O/S RETAINER	Not Necessary	162.80 FL	*- FL
8	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
9	1		*REAR END PANEL	Repair	581.90 FL	*- FL
10	1		*REAR END PANEL INNER TRIM	Not Necessary	253.50 FL	*- FL
11	4		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	16.00 FS	*- FS
12	1		*REAR O/S TAIL LAMP	Cracked	878.20 FL	*391.00 FL
13	1		*REAR O/S TAIL LAMP CLIPS	Necessary	30.00 FS	*10.00 FS
14	1		*REAR BOOT COVER	Dented	874.40 FL	*874.40 FL
15	1		*REAR BOOT COVER WEATHERSTRIP	Not Necessary	174.40 FL	*- FL
16	1		*REAR BOOT COVER EMBLEM	Necessary	71.50 FL	*71.50 FL
17	1		*REAR BOOT COVER COROLLA EMBLEM	Necessary	61.70 FL	*61.70 FL
18	1		*REAR BOOT COVER ALTIS EMBLEM	Necessary	67.70 FL	*67.70 FL
19	1		*REAR O/S BOOT COVER REFLECTOR	O/S Cracked	710.20 FL	*358.00 FL
20	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	164.40 FL	*- FL
21	1		*REAR BOOT COVER MOULDING CHROME	Cut	287.10 FL	*287.10 FL
22	4		*REAR BOOT COVER MOULDING CLIPS	Necessary	16.00 FS	*16.00 FS
23	1		*REAR BOOT COVER LOCK(UPPER)	Damaged	291.60 FL	*291.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,132.20	3,215.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,435.05	739.75
Total Parts (\$\$)	4,697.15	2,475.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	500.00
2	TO SPRAY PAINTING	New	800.00	400.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	50.00
4	TO CHECK WIRING	New	80.00	30.00
5	TO RE-SEAL ANTI RUST	New	80.00	30.00
Gross Labour Cost (\$)			1,840.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >