

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22007385/RPA3Q2**Date:** 10/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SGY9888G **Insured Vehicle No :** SLR4118G

Date of Loss: 22/07/2022 Nature of Claim: TP Claim No: MFL2022D0003930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY9888G**
 Make & Model: BMW 116D, 1.5 D 5DR HATCH DSC LED (A) Engine No: 36029867B37D15A
 Reg. Date: 28/04/2017 (Man. Year: 2017) Chassis No: WBA1V720205G86542
 Colour: Grey Odometer: 42537 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,750.70	1,179.70	571.00	32.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,189.00	2,172.00	1,017.00	31.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,939.70	3,351.70	1,588.00	32.15
+ GST 7.00/7.00% (S\$)	345.78	234.62	111.16	32.15
Nett Amount (S\$)	5,285.48	3,586.32	1,699.16	32.15
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,833.77		

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 22/08/2022 Inspected At:

 Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance
 Centre
 Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	144	BMW 116D 1.5 D 5DR HATCH DSC LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY9888G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	424.85 FS	*- FS
3	1		*HOLDER CAMERA SYSTEM	Not Necessary	36.50 FS	*- FS
4	1		*HOLDER AERIAL	Not Necessary	26.70 FS	*- FS
5	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	39.95 FS	*- FS
6	1		*(S/L) LH PROTECTION FOIL	Not Necessary	10.90 FS	*- FS
7	1		*(S/L) RH PROTECTION FOIL	Not Necessary	10.90 FS	*- FS
8	1		*REAR BUMPER PRIMED (RFC)	Deformed	1,019.95 FS	*1,019.95 FS
9	1		*SET REAR PDC HOLDER	Necessary	26.70 FS	*26.70 FS
10	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	21.20 FS	*- FS
11	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (S\$)						1,750.70 1,179.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING SYSTEM AT REAR SECTION FOR PROPER FUNCTION	New	168.00	168.00
2	REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMEN ETC	New	1,275.00	850.00
3	PAINTING REAR BUMPER	New	1,038.00	986.00
4	TO REMOVE AND INSTALL FUSE BOX AT THE FRONT SECTION TO FACILITATE REPAIR	New	531.00	0.00
5	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (S\$)			3,189.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >