

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007386/ECE2**Date:** 06/12/2022**REFERENCE**

Insured/Claimant:	NORMALIS BINTE ALWI	Policy No:	7210059193	
Date of Loss:	29/07/2022	Nature of Claim:	OD	Claim No: 9739015681SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA2262B		
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)	Engine No:	DFY268691
Reg. Date:	12/06/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGY7MA095134
Colour:	Grey	Odometer:	21378 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,306.00	15,634.88	16,671.12	51.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,324.00	9,189.00	7,135.00	43.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,630.00	24,823.88	23,806.12	48.95
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	48,230.00	24,423.88	23,806.12	49.36
+ GST 7.00/7.00% (S\$)	3,376.10	1,709.67	1,666.43	49.36
Nett Amount (S\$)	51,606.10	26,133.55	25,472.55	49.36

INSPECTION

Date of Assignment:	03/08/2022		
Date Inspected:	02/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,677.00 FS	*1,341.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	290.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	260.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Broken	433.00 FS	*346.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	265.00 FS	*212.00 FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	134.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Crushed	326.00 FS	*260.40 FS
8	2		*FRONT BUMPER SPOILER COVER TRIM - LH / RH	Cut	208.00 FS	*165.60 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Broken	342.00 FS	*136.40 FS
10	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	86.00 FS	*- FS
11	1		*RADIATOR GRILLE	Broken	932.00 FS	*745.60 FS
12	1		*FRONT CLOSING ELEMENT - CENTER	Broken	210.00 FS	*168.00 FS
13	2		*FRONT LOW & HIGH TONE SIGNAL HORN - LH / RH	Not Necessary	314.00 FS	*- FS
14	8		*SPRING SHACKLE - LH / RH	Not Necessary	247.00 FS	*- FS
15	4		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	1,116.00 FS	*- FS
16	4		*FRONT PARKING AID SEAL RING	Not Necessary	32.00 FS	*- FS
17	1		*SET FRONT BUMPER WIRING	Not Necessary	252.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	120.00 FS	*95.60 FS
19	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	748.00 FS	*598.00 FS
20	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	20.00 FS	*15.52 FS
21	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	108.00 FS	*- FS
22	1		*FRONT BUMPER TOP COVER	Crushed	93.00 FS	*74.00 FS
23	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
24	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
25	2		*FRONT FENDER - LH / RH	Repair	2,482.00 FS	*- FS
26	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	64.00 FS	*- FS
27	7		*POP RIVET	Not Necessary	27.00 FS	*- FS
28	6		*FRONT FENDER BRACKET - LH / RH	Not Necessary	223.00 FS	*- FS
29	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	196.00 FS	*- FS
30	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
31	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	366.00 FS	*- FS
32	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	44.00 FS	*- FS
33	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	125.00 FS	*- FS
34	1		*BONNET	Dented	3,271.00 FS	*2,616.80 FS
35	2		*LID HINGE - LH / RH	Not Necessary	136.00 FS	*- FS
36	1		*BONNET ATTACHMENT PARTS	Not Necessary	256.00 FS	*- FS
37	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	30.00 FS	*23.60 FS
38	2		*FRONT FENDER COVER - LH / RH	Not Necessary	92.00 FS	*- FS
39	2		*BONNET STRIKER - LH / RH	Not Necessary	246.00 FS	*- FS
40	1		*BONNET RELEASE ELEMENT	Not Necessary	65.00 FS	*- FS
41	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
42	2		*BONNET LID LOCK - LH / RH	Not Necessary	455.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	61.00 FS	*- FS
44	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
45	1		*BONNET LID LOCK CABLE - RH	Not Necessary	82.00 FS	*- FS
46	1		*FRONT PLENUM CHAMBER COVER	Not Necessary	177.00 FS	*- FS
47	1		*BONNET GAS FILLED STRUT	Not Necessary	110.00 FS	*- FS
48	2		*FRONT HEADLIGHT - LH / RH	Broken	8,168.00 FS	*6,534.40 FS
49	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	422.00 FS	*- FS
50	1		*LIFT CYLINDER HOSE	Not Necessary	108.00 FS	*- FS
51	1		*WASH WATER RESERVOIR	Crushed	179.00 FS	*143.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LOCK CARRIER	Broken	990.00 FS	*792.00 FS
53	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
54	1		*A/C CONDENSER	Bent	569.00 FS	*454.80 FS
55	1		*RADIATOR FAN RING	Not Necessary	1,061.00 FS	*- FS
56	1		*COOLANT ADDITIONAL RADIATOR	Not Necessary	959.00 FS	*- FS
57	1		*RADIATOR FAN RING	Not Necessary	1,339.00 FS	*- FS
58	6		*READY-MIX COOLANT	Necessary	282.00 FS	*237.12 FS
59	2		*RADIATOR AIR GUIDE - LH / RH	Broken	84.00 FS	*65.76 FS
60	1		*RADIATOR FRONT SEAL - RH	Broken	14.00 FS	*11.12 FS
61	1		*RADIATOR AIR GUIDE - LOWER CENTRE	Broken	59.00 FS	*46.64 FS
62	1		*FRONT INTAKE AIR DUCT COVER	Broken	30.00 FS	*23.84 FS
63	1		*FRONT INTAKE AIR GUIDE (3PCS)	Broken (2pcs only)	130.00 FS	*74.56 FS
64	1		*AIR INTAKE WATER DRAINAGE HOSE	Not Necessary	37.00 FS	*- FS
65	1		*AIR FILTER	Broken	310.00 FS	*269.20 FS
66	1		*INTAKE AIR GUIDE FLAP	Broken	27.00 FS	*21.36 FS
67	1		*FRONT NO PLATE	Missing	60.00 FS	*60.00 FS
68	1		*SUNDRIES	Necessary	500.00 FS	*15.20 FS
69	1		*OUTER TEMPERATURE SENSOR (Supplementary)	Broken	64.00 FS	*51.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	32,306.00	15,634.88
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY FOR BOTH FRONT DOOR	New	560.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, BOTH FRONT FENDER AND BOTH FRONT DOORS	New	6,000.00	2,475.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			16,324.00	9,189.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >