

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007388/ANY3E2**Date:** 12/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00004402206
Claimant Vehicle No :	PC7756B	Insured Vehicle No :	PA5257Z
Date of Loss:	01/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205361/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7756B	Engine No:	1GD8362600
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	GDH2232001194
Reg. Date:	08/04/2019 (Man. Year: 2019)	Odometer:	175140 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,008.71	18,927.48	18,081.23	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,190.00	3,850.00	3,340.00	46.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	44,198.71	22,777.48	21,421.23	48.47
Approved Total (Overridden) (\$\$)		18,200.00		
Nett Amount (\$\$)	44,198.71	18,200.00	25,998.71	58.82

INSPECTION

Date of Assignment:	03/08/2022	
Date Inspected:	02/08/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	11.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Oct 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7756B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	571.60 FL	*571.60 FL
2	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	97.40 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP	Not Necessary	591.60 FL	*- FL
4	2		*FRONT BUMPER TOWING COVER	Not Necessary	50.20 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	226.40 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	148.70 FL	*75.00 FL
7	2		*FRONT ADBLUE TANK BRACKET	Not Necessary	330.60 FL	*- FL
8	1		*HEADLAMP	N/S Cut	6,066.40 FL	*2,380.00 FL
9	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	38.80 FL	*- FL
10	1		*CENTRE GRILLE BASE	Cracked	568.90 FL	*568.90 FL
11	1		*CENTRE GRILLE LOWER COVER GARNISH	Not Necessary	383.70 FL	*- FL
12	1		*CENTRE GRILLE UPPER COVER GARNISH	Not Necessary	221.80 FL	*- FL
13	1		*FRONT WIPER GARNISH	Not Necessary	639.80 FL	*- FL
14	1		*FRONT WIPER GARNISH SIDE JOINT LH	Not Necessary	26.80 FL	*- FL
15	1		*FRONT WINDSCREEN MOULDING	Not Necessary	81.80 FL	*- FL
16	1		*WASHER TANK	Not Necessary	286.00 FL	*- FL
17	1		*BONNET	Repair	1,020.30 FL	*- FL
18	2		*BONNET HINGE	Not Necessary	119.60 FL	*- FL
19	1		*BONNET LOCK	Not Necessary	93.90 FL	*- FL
20	1		*AIR CLEANER	Cracked	780.01 FL	*780.01 FL
21	1		*AIR DUCT	Not Necessary	115.80 FL	*- FL
22	1		*FRONT CORNER PANEL LH	Dented	268.40 FL	*268.40 FL
23	1		*FRONT CORNER PANEL TOP RUBBER LH	Not Necessary	24.50 FL	*- FL
24	1		*SET FRONT CORNER VIEW MIRROR LH	Cracked	1,060.00 FL	*973.00 FL
25	1		*FRONT CORNER VIEW MIRROR SUPPORT BRACKET	Cracked	268.30 FL	*268.30 FL
26	1		*FRONT STEP PANEL GARNISH LH	Distorted	204.90 FL	*204.90 FL
27	1		*FRONT STEP INNER PANEL	N/S Dented	270.00 FL	*135.00 FL
28	1		*FRONT DOOR PILLAR LH (OUTER)	Repair	542.80 FL	*- FL
29	1		*FRONT DOOR PILLAR LH (INNER)	Repair	317.20 FL	*- FL
30	1		*FRONT DOOR SIDE MIRROR LH (COMPLETE SET)	Damaged	1,492.90 FL	*1,492.90 FL
31	2		*FRONT DOOR	Dented	3,774.20 FL	*3,350.00 FL
32	2		*FRONT DOOR ARCH RUBBER	Not Necessary	157.20 FL	*- FL
33	1		*FRONT DOOR GLASS LH	Not Necessary	525.30 FL	*- FL
34	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	258.10 FL	*- FL
35	1		*FRONT DOOR OUTERSTRIP LH	Not Necessary	125.80 FL	*- FL
36	1		*FRONT DOOR INNER LOCK LH	Not Necessary	578.30 FL	*- FL
37	2		*FRONT DOOR HINGE LH	Not Necessary	170.40 FL	*- FL
38	1		*FRONT DOOR CHECKER LH	Not Necessary	183.80 FL	*- FL
39	2		*FRONT DOOR WEATHERSTRIP	Not Necessary	576.20 FL	*- FL
40	1		*FRONT DOOR INNER TRIM LH	Not Necessary	806.20 FL	*- FL
41	1		*FRONT DOOR WIRE HOLDER LH	Cracked	105.20 FL	*105.20 FL
42	1		*FRONT SUPPORT PANEL	Not Necessary	496.90 FL	*- FL
43	2		*FRONT WHEEL HOUSE ARCH RUBBER	Not Necessary	178.20 FL	*- FL
44	2		*FRONT LOWER ARM	Bent	1,380.00 FL	*1,380.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT UPPER ARM	Bent	1,300.00 FL	*1,300.00 FL
46	2		*FRONT SHOCK ABSORBER	Damaged	930.00 FL	*930.00 FL
47	2		*FRONT KNUCKLE ARM	N/S Damaged / O/S Cracked	1,490.00 FL	*1,490.00 FL
48	1		*FRONT BRAKE HOSE RH	Not Necessary	186.30 FL	*- FL
49	2		*FRONT LINKAGE	Not Necessary	210.00 FL	*- FL
50	2		*FRONT ABS SENSOR	Not Necessary	794.40 FL	*- FL
51	1		*FRONT STEERING RACK & PINION	Bent	1,965.00 FL	*1,965.00 FL
52	1		*ENGINE UNDER COVER	Not Necessary	465.20 FL	*- FL
53	1		*RADIATOR	Cracked	2,577.30 FL	*1,588.00 FL
54	1		*AIR CON CONDENSER	Not Necessary	1,949.10 FL	*- FL
55	1		*AIR CON PIPE (SMALL)	Not Necessary	364.00 FL	*- FL
56	1		*AIR CON PIPE (BIG)	Not Necessary	475.00 FL	*- FL
57	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
58	1		*FRONT BUMPER LOWER SPOILER	Damaged	800.00 FS	*600.00 FS
59	1		*ADBLUE	Necessary	200.00 FS	*60.00 FS
60	1		*SET CENTRE GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
61	1		*SET FRONT WIPER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
62	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
64	1		*BONNET SEALANT	Not Necessary	120.00 FS	*- FS
65	1		*SET FRONT STEP PANEL GARNISH RH CLIP	Necessary	50.00 FS	*20.00 FS
66	1		*SET FRONT STEP PANEL GARNISH TOP CHROME	Damaged	300.00 FS	*150.00 FS
67	1		*FRONT DOOR PILLAR RH (OUTER) SEALANT	Not Necessary	120.00 FS	*- FS
68	1		*SET FRONT DOOR OUTER PROTECTOR	Not Necessary	500.00 FS	*- FS
69	2		*FRONT DOOR SEALANT	Not Necessary	240.00 FS	*- FS
70	1		*SET FRONT DOOR VISOR	Cracked	200.00 FS	*120.00 FS
71	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
72	1		*FRONT DOOR GLASS SOLAR FILM LH	Not Necessary	350.00 FS	*- FS
73	1		*FRONT WHEEL TYRE	O/S Cut	760.00 FS	*200.00 FS
74	2		*FRONT WHEEL RIM	Cut	900.00 FS	*900.00 FS
75	1		*BRAKE OIL	Necessary	500.00 FS	*100.00 FS
76	1		*FRONT CROSS MEMBER	Bent	1,892.10 FL	*1,892.10 FL
77	1		*FRONT ADBLUE TANK	Cracked	1,308.30 FL	*585.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	47,541.61	24,503.31
- List Item Discount on L Items 25.00/25.00% (\$\$)	10,532.90	5,575.83
Total Parts (\$\$)	37,008.71	18,927.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,800.00	1,400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	1,200.00
3	TUFF COAT	New	250.00	120.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
6	REMOVE AND REFIX RADIATOR	New	120.00	60.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	TRANSFER BOTH FRONT DOOR MECHANISM	New	160.00	80.00
10	REMOVE AND REFIX DOOR WINDOW GLASS	New	100.00	80.00
11	REMOVE ANF REFIX DASHBOARD	New	850.00	0.00
12	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
13	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	550.00
14	REMOVE AND REFIX BOTH FRONT WHEEL BEARING	New	120.00	0.00
15	REMOVE AND REFIX STEERING RACK AND PINION	New	500.00	120.00
16	REMOVE AND REFIX ADBLUE TANK	New	150.00	50.00
17	FOUR WHEEL ALIGNMENT	New	120.00	80.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,190.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >