

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007389/UVY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00249582101

Claimant Vehicle No : SMF5529Z **Insured Vehicle No :** SKG7054G

Date of Loss: 29/07/2022 Nature of Claim: TP Claim No: SNM22D205373/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF5529Z**

Make & Model: VOLKSWAGEN PASSAT, 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A) Engine No: CJS284163

Reg. Date: 16/11/2018 (Man. Year: 2018) Chassis No: WVWZZZ3CZKE004537

Colour: Black Odometer: 74524 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,930.78	2,415.95	2,514.83	51.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,050.00	720.00	40.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,700.78	3,465.95	3,234.83	48.28
+ GST 7.00/7.00% (S\$)	469.05	242.62	226.43	48.27
Nett Amount (S\$)	7,169.83	3,708.57	3,461.26	48.28

INSPECTION

Date of Assignment: 02/08/2022

Date Inspected: 23/08/2022 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2022)

Parts: 143 VOLKSWAGEN PASSAT 1.8 B8 TFSI AT SR 17W 3G24JZ HUD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF5529Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,537.24 FL	*1,537.24 FL
2	10		*REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
3	1		*REAR BUMPER SIDE HOLDER -LH /RH	N/S Not Necessary /O/S Cracked	96.80 FL	*48.40 FL
4	1		*REAR BUMPER SENSOR	Serviceable	417.70 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	487.80 FL	*- FL
6	1		*REAR BUMPER RETAINER	Not Necessary	74.40 FL	*- FL
7	1		*REAR BUMPER LOWER CHROME -CENTER	Cracked	276.85 FL	*276.85 FL
8	1		*REAR BUMPER LOWER CHROME -LH	Necessary	233.45 FL	*233.45 FL
9	1		*REAR BUMPER LOWER CHROME -RH	Necessary	233.45 FL	*233.45 FL
10	1		*REAR PANEL	Repair	1,397.96 FL	*- FL
11	1		*REAR BUMPER SENSOR WIRE	Serviceable	362.45 FL	*- FL
12	1		*REAR BUMPER LOWER SKIRTING	Distorted	285.55 FL	*285.55 FL
13	1		*REAR NUMBER PLATE WITH CASING	Bent	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,473.65	2,679.94
- List Item Discount on L Items 10.00/10.00% (\$\$)	542.87	263.99
Total Parts (\$\$)	4,930.78	2,415.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,ON REAR PANEL ,REAR BOOT ,REMOVE ,REPLACE ACCIDENT PARTS	New	700.00	400.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	500.00
3	TO CHECK WIRING	New	40.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE,REFIT REAR GARNISH	New	80.00	80.00
6	TO TUFF -KOTE	New	50.00	0.00
Gross Labour Cost (\$)			1,770.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >