



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22007390/Ucy3m4	
			Date: 04/10/2022	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 5960K	Veh. Inspected	XE 7002M	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D18792207	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	03/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU CYH52T (M)	c.c	15681	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JALCYH52TM7000117	Colour	GREEN	
Odometer	21238 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5 (D/D)	BRIDGESTONE	5/5 5/5 mm	
L/H Front Tyre	275/70 R22.5 (D/D)	BRIDGESTONE	5/5 5/5 mm	
R/H Rear Tyre	275/70 R22.5 (D/D)	ANNAITE	5/5 5/5 mm	
L/H Rear Tyre	275/70 R22.5 (D/D)	ANNAITE	5/5 5/5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/06/2022	Inspection Date	07/09/2022	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	