



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 2962U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SYM FRONT SUSPENSION (LEFT)	DISTORTED / SHIFTED / GRAZED	400.00	400.00
1	SYM FRONT SUSPENSION (RIGHT)	DISTORTED / SHIFTED	400.00	400.00
1	SYM TRIPLE CLAMP (BOTTOM)	SERVICEABLE	350.00	-
1	SYM HANDLE BAR	DISTORTED	150.00	150.00
1	SYM STEERING CONE BEARING	NECESSARY	120.00	120.00
1	SYM FRONT HEADLIGHT	BROKEN / MISSING	380.00	380.00
1	SM FRONT HEADLIGHT BRACKET	SERVICEABLE	80.00	-
1	SYM FRONT HEADLIGHT WIRING HARNESS	TO REPAIR SEE LABOUR	110.00	-
1	SYM FRONT WHEEL RIM	TO REPAIR SEE LABOUR	380.00	-
2	SYM FRONT WHEEL SEAL	NOT NECESSARY	30.00	-
2	SYM FRONT WHEEL BEARING	NOT NECESSARY	70.00	-
1	SYM FRONT WHEEL SHAFT	TO REPAIR SEE LABOUR	50.00	-
1	SYM FRONT SIGNAL LIGHT (LEFT)	NOT NECESSARY	100.00	-
1	SYM FRONT SIGNAL LIGHT (RIGHT)	CRACKED	100.00	100.00
1	SYM MIRROR (LEFT)	CRACKED / GRAZED	140.00	60.00
1	SYM MIRROR (RIGHT)	NOT NECESSARY	140.00	-
1	SYM FRONT HEAD COWL FAIRING (UPPER)	DISTORTED / SCRATCHED	120.00	120.00
1	SYM FRONT HEAD COWL FAIRING (LOWER)	BROKEN	380.00	380.00
1	SYM FRONT MUDGUARD FAIRING	GRAZED	180.00	180.00
1	SYM FRONT BRAKE DISC	TO REPAIR SEE LABOUR	140.00	-
1	SYM FRONT BRAKE HOSE	CUT	35.00	35.00
1	SYM FRONT BRAKE MASTER CYLINDER (LEFT)	SERVICEABLE	220.00	-
1	SYM FRONT WINDSHIELD	BROKEN	220.00	220.00
1	SYM SIDE FAIRING BELLY PEN (LEFT)	SERVICEABLE	110.00	-
1	SYM SIDE FAIRING BELLY PEN (RIGHT)	SERVICEABLE	110.00	-
1	SYM FLOORBOARD (RIGHT)	SERVICEABLE	110.00	-

Report Ref No. CS3/LPC21009526/Vcy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET SYM FLOORBOARD STEP RUBBERS (SMALL) (LEFT)	MISSING	40.00	40.00
1	SET SYM FLOORBOARD STEP RUBBER (BIG) (LEFT)	MISSING	60.00	60.00
1	SYM LEGSHIELD (CENTER - COMPARTMENT PANEL)	NOT NECESSARY	250.00	-
1	SYM LEGSHIELD (CENTER - COMPARTMENT PANEL COVER)	GRAZED	45.00	45.00
1	SYM LEFT SIDE MIDDLE FAIRING - (SILVER)	MISSING	80.00	80.00
1	SYM REAR SIDE FAIRING (LEFT)	CRACKED / GRAZED	280.00	280.00
1	SYM REAR SIDE FAIRING (RIGHT)	TO REPAIR SEE LABOUR	280.00	-
2	SYM REAR SIDE FAIRING PROTECTORS	GRAZED (1PC ONLY)	70.00	35.00
1	SYM REAR TAIL LIGHT	BROKEN	295.00	195.00
1	SYM REAR NUMBER PLATE HOLDER	BROKEN	95.00	95.00
1	SYM REAR NUMBER PLATE LIGHT ASSEMBLY	CRACKED	80.00	80.00
1	SYM REAR NUMBER PLATE REFLECTOR	SCRATCHED	25.00	25.00
1	SYM REAR BOX RACK	SERVICEABLE	280.00	-
1	SYM REAR BOX RACK BRACKET	TO REPAIR SEE LABOUR	60.00	-
1	SET SYM BAR END	GRAZED / MISSING	90.00	90.00
2	SYM PILLION FOOTRESTS	GRAZED	110.00	110.00
2	SYM PILLION FOOTREST PINS	SERVICEABLE	20.00	-
2	SYM PILLION FOOTREST BEARINGS	SERVICEABLE	20.00	-
1	SYM EXHAUST MUFFLE	NOT NECESSARY	750.00	-
1	SYM EXHAUST COVER (BIG)	GRAZED	75.00	75.00
1	SYM EXHAUST COVER (SMALL)	GRAZED	50.00	50.00
1	SYM EXHAUST GASKET	NECESSARY	15.00	15.00
1	SYM BRAKE LEVER (RIGHT)	GRAZED	45.00	45.00
1	SYM AIR BOX COVER (UPPER)	NOT NECESSARY	85.00	-
1	SYM BELLY PEN (UNDER COVER)	NOT NECESSARY	125.00	-
1	SYM FLOORBOARD (LEFT)	CRACKED	110.00	110.00
	LESS 10% DISCOUNT		-	-397.50
			8,060.00	3,577.50
	<u>SPECIAL NETT ITEMS</u>			
1	LIQUIMOLY FRONT BRAKE FLUID (SN)	NOT NECESSARY	15.00	-

Report Ref No. CS3/LPC21009526/Vcy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	NECESSARY	15.00	10.00
1	REAR NUMBER PLATE (SN)	NECESSARY	20.00	15.00
1	HANDPHONE HOLDER - (LEFT) (SN)	BROKEN	50.00	50.00
			100.00	75.00
	LABOUR			
	TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE, FRONT BRAKE DISC. }		300.00	450.00
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF SYM FRONT HEADLIGHT WIRING HARNESS, SYM FRONT WHEEL RIM, SYM FRONT WHEEL SHAFT, SYM FRONT BRAKE DISC, SYM REAR SIDE FAIRING (RIGHT) AND SYM REAR BOX RACK BRACKET. }		650.00	-
	TO RESPRAY PAINT ON THE AFFECTED AREA.		400.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.		550.00	150.00
	TOWING - WORKSHOP TO ACCIDENT REPORTING CENTER. }		60.00	60.00
	TOWING - ACCIDENT REPORTING CENTER TO WORKSHOP. }		60.00	-
			2,020.00	860.00
GRAND TOTAL			10,180.00	4,512.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00
---	--	--	-----------------

Report Ref No. CS3/LPC21009526/Vcy3e2-1

MARKET VALUE: \$4,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$294.00=NETT VALUE: \$3,706.00

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.