

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22007399/Rcy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 16/08/2022 SINGAPORE 068811 ATTN: KHOR SAW THENG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLF 1074G** SMF 5843R Veh. Inspected Policy No. GA259099 Coverage (\$) 0.00 Claim No. S2M0480N Excess (\$) 0.00 KHOR SAW THENG **Assign Date** 03/08/2022 Assign From **Vehicle Particulars & Condition** 2. HYUNDAI TL TUCSON FL 1.6 Make & Model 1591 C.C GLS T Engine No. **HIDDEN** Year of Reg. 2018 Chassis No. KMHJ3812VKU804807 Colour **GREY** 134499 KM IN ORDER Odometer Steering **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 215/60 R16 YOKOHAMA 6 mm R/H Front Tyre 215/60 R16 YOKOHAMA L/H Front Tyre 6 mm R/H Rear Tyre 215/60 R16 YOKOHAMA 6 mm 215/60 R16 YOKOHAMA L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. 5. **General Information Accident Date** 02/08/2022 Inspect Date / Time 04/08/2022 (03:08 PM) HONG MOTOR SERVICES Survey held at BLK 5035 ANG MO KIO IND PARK 2 #01-365 SINGAPORE 569538 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22007399/Rcy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days