

Your Ref: 2022 - 62

Date: 24th August 2022

Our Ref: CS1/SCD22007400/Rqy3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMB 1518C
INSURED VEHICLE: QX 2310P
ACCIDENT DATE: 30/05/2022**

We thank you for your instruction on 01/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMB 1518C from M/s Strides Automotive Services Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SMB 1518C.
- c) Colour damaged vehicle photographs of SMB 1518C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMB 1518C
Make & Model	: Man NL 320F (A22) 11L Auto ABS Turbo
Chassis Number	: WMAA22ZZ8E7002303
Year of Registration	: 2014
Engine Capacity	: 10518 cc

2. We recommend that the repairs of the entire damage require about 1 (One) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1518C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIGNAL LAMP LED	DAMAGED	1,274.10	1,274.10
2	STOP LAMP LED	DAMAGED	2,283.40	2,283.40
1	COVER REAR TAIL LAMP RH	TO REPAIR SEE LABOUR	974.70	-
	LESS 10% DISCOUNT		-453.22	-355.75
			4,078.98	3,201.75
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER REAR TAIL LAMP RH.		795.00	265.00
	TO PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		708.00	538.00
			1,503.00	803.00
GRAND TOTAL			5,581.98	4,004.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CS1/SCD22007400/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.