

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22007403/EVY3M4**Date:** 15/09/2022**REFERENCE**

Insured/Claimant:	LIM KENG GOY	Policy No:	DMPG21013802	
Date of Loss:	27/07/2022	Nature of Claim:	OD	Claim No: CDMPG22001494

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMF8988L</b>		
Make & Model:	LEXUS RX300, 2.0 5DR SUV (4WD) LUXURY (A)	Engine No:	8ARW920833
Reg. Date:	08/10/2018 (Man. Year: 2018)	Chassis No:	JTJBAMCA802060157
Colour:	White	Odometer:	94142 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$182,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R20	Rear Tyre Size:	235/55 R20
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	27,988.20	5,974.20	22,014.00	78.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,881.50	2,407.50	2,474.00	50.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>32,869.70</b>	<b>8,381.70</b>	<b>24,488.00</b>	<b>74.50</b>
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	32,169.70	7,681.70	24,488.00	76.12
<b>+ GST 7.00/7.00% (S\$)</b>	2,251.88	537.72	1,714.16	76.12
<b>Nett Amount (S\$)</b>	<b>34,421.58</b>	<b>8,219.42</b>	<b>26,202.16</b>	<b>76.12</b>

**INSPECTION**

Date of Assignment:	03/08/2022	
Date Inspected:	04/08/2022	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 15 Sep 2022)

**Parts:** M1-SUV    LEXUS RX300 2.0 5DR SUV (4WD) LUXURY (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMF8988L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNIT, HEADLAMP	Not Necessary	7,900.10 FS	*- FS
2	1		*UNIT, HEADLAMP	Not Necessary	7,900.10 FS	*- FS
3	1		*MOULDING, RADIATOR (CHROME UPP)	Broken	642.80 FS	*642.80 FS
4	1		*MOULDING, RADIATOR (CHROME LOWER)	Broken	1,051.80 FS	*1,051.80 FS
5	1		*SEAL, HOOD TO	Necessary	55.40 FS	*55.40 FS
6	1		*GRILLE, RADIATOR (UPP)	Broken	1,433.40 FS	*1,433.40 FS
7	1		*GRILLE, RADIATOR (LOW)	Broken	354.30 FS	*354.30 FS
8	1		*EMBLEM, SYMBOL	Not Necessary	516.60 FS	*- FS
9	1		*RETAINER, ULTRASONIC	Necessary	20.90 FS	*20.90 FS
10	1		*RETAINER, ULTRASONIC	Necessary	20.90 FS	*20.90 FS
11	1		*RETAINER, FR BUMPER	Broken	135.70 FS	*135.70 FS
12	1		*RETAINER, FR BUMPER	Broken	135.70 FS	*135.70 FS
13	1		*REINFORCEMENT	Not Necessary	802.50 FS	*- FS
14	1		*ABSORBER, FR BUMPER	Broken	120.90 FS	*120.90 FS
15	1		*ABSORBER, FR BUMPER	Not Necessary	199.70 FS	*- FS
16	1		*COVER, FR BUMPER	Broken	1,223.90 FS	*1,223.90 FS
17	1		*BRACKET, FOG LAMP	Not Necessary	169.20 FS	*- FS
18	1		*BRACKET, FOG LAMP	Not Necessary	173.80 FS	*- FS
19	1		*COVER, FR BUMPER	Not Necessary	52.10 FS	*- FS
20	1		*COVER, FR BUMPER	Broken	52.10 FS	*52.10 FS
21	1		*COVER, FOG LAMP, RH	Not Necessary	134.40 FS	*- FS
22	1		*COVER, FOG LAMP, LH	Not Necessary	134.40 FS	*- FS
23	1		*GARNISH, RADIATOR	Not Necessary	81.90 FS	*- FS
24	1		*GARNISH, RADIATOR	Cracked	81.90 FS	*81.90 FS
25	1		*COVER, FR BUMPER ARM	Not Necessary	108.40 FS	*- FS
26	1		*COVER, FR BUMPER ARM	Not Necessary	87.40 FS	*- FS
27	1		*COVER, FR BUMPER	Not Necessary	145.80 FS	*- FS
28	1		*COVER, FR BUMPER	Not Necessary	145.80 FS	*- FS
29	1		*GUARD, FR BUMPER	Broken	173.80 FS	*173.80 FS
30	1		*BRACKET, FR BUMPER	Broken	173.80 FS	*173.80 FS
31	2		*RETAINER, OUTSIDE	Necessary	8.60 FS	*8.60 FS
32	2		*CLIP	Necessary	5.60 FS	*5.60 FS
33	2		*RETAINER, ULTRASONIC	Necessary	41.80 FS	*41.80 FS
34	1		*LAMP ASSY, FOG	Not Necessary	516.00 FS	*- FS
35	1		*LAMP ASSY, FOG, LH	Not Necessary	516.00 FS	*- FS
36	1		*LAMP ASSY,	Not Necessary	1,199.90 FS	*- FS
37	1		*LAMP ASSY,	Not Necessary	1,199.90 FS	*- FS
38	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
39	1		*BRACKET, WASHER,	Necessary	36.60 FS	*36.60 FS
40	1		*BRACKET, WASHER,	Necessary	36.60 FS	*36.60 FS
41	1		*DEFLECTOR, RADIATOR	Broken	117.70 FS	*117.70 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **27,988.20**    **5,974.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)	New	216.50	216.50
2	REMOVE/REFIX FRONT PARKING SENSORS. (NETT)	New	216.50	216.50
3	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT, R/H AND L/H HEADLAMP PANEL AND FIT NEW PARTS	New	2,598.00	866.00
4	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	1,484.00	742.00
5	TO RESET ECU & REPROGRAMME. (NETT)	New	216.50	216.50
6	SUPPLY REGN PLATE (PO# ) FRONT (NETT) SPECIAL PLATE	New	150.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,881.50</b>	<b>2,407.50</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >