

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22007410/RQY3Q2**Date:** 26/09/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SNC4306K **Insured Vehicle No :** SMN312Y
 Date of Loss: 25/07/2022 Nature of Claim: TP Claim No: DMCF2200149H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC4306K**
 Make & Model: TOYOTA COROLLA ALTIS, 1.8 E HYBRID ELEGANCE (2WD) (A) Engine No: 2ZRY781938
 Reg. Date: 20/10/2021 (Man. Year: 2021) Chassis No: MR2BZ3BE400008510
 Colour: Blue Odometer: 74378 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,130.75	3,216.48	5,914.27	64.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,120.00	610.00	35.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,860.75	4,336.48	6,524.27	60.07
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	10,860.75	3,450.00	7,410.75	68.23
+ GST 7.00/7.00% (S\$)	760.25	241.50	518.75	68.23
Nett Amount (S\$)	11,621.00	3,691.50	7,929.50	68.23

INSPECTION

Date of Assignment: 03/08/2022
 Date Inspected: 04/08/2022 Inspected At: 60 Jalan Lam Huat, #05-21 Carros
 Estimated Period of Repair: 5.0 days Repairer: My Car Consultant Pte Ltd (HQ)

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2022)**Parts:** 143 TOYOTA COROLLA ALTIS 1.8 E HYBRID ELEGANCE (2WD) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SNC4306K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,354.00 FL	*924.15 FL
2	1		*BONNET RUBBER	Serviceable	18.00 FL	*- FL
3	1		*BONNET LOCK	Serviceable	312.00 FL	*- FL
4	2		*BONNET HINGES	Serviceable	136.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	798.00 FL	*581.10 FL
6	1		*FRONT BUMPER REINFORCEMENT	Serviceable	398.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Cracked	198.00 FL	*198.00 FL
8	2		*FRONT BUMPER SIDE RETAINER	Serviceable	196.00 FL	*- FL
9	1		*FRONT BUMPER CENTRE GRILLE	Cracked	612.00 FL	*286.00 FL
10	2		*FRONT BUMPER FOGLAMP COVER	Serviceable	136.00 FL	*- FL
11	1		*FRONT GRILLE	Scratched	590.00 FL	*446.00 FL
12	1		*FRONT GRILLE TOP RUBBER	Serviceable	75.00 FL	*- FL
13	1		*FRONT GRILLE TOP GARNISH	Serviceable	198.00 FL	*- FL
14	1		*FRONT GRILLE LOGO	Scratched	187.00 FL	*98.00 FL
15	1		*AIR CLEANER AIR DUCT	Serviceable	212.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Repair	825.00 FL	*- FL
17	1		*HEADLAMP LED	O/S Cracked	5,596.00 FL	*1,588.72 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*35.00 FS
20	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*SET FRONT BUMPER LOWER COVER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,091.00	4,246.97
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,960.25	1,030.49
Total Parts (\$\$)	9,130.75	3,216.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	500.00
2	PANEL BEATING ON AFFECTED AREAS	New	600.00	500.00
3	REMOVE AND REFIR FRONT SUPPORT ,RADIA CONDENSOR	New	300.00	60.00
4	RE FOCUS FRONT HEADLAMP }	New	80.00	30.00
5	TO CHECK ELECTRICAL WIRING }	New	100.00	0.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	50.00	30.00
			Gross Labour Cost (\$)	1,730.00
				1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >